

福星摩多工廠

FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758
Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006
E-mail: ryan@kanfs.net / patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883
Tel: (65) 6481 5150 • Fax: (65) 6481 8633

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD

#02-01 UOI BUILDING
SINGAPORE 068909

VEHICLE NO.

: GBG4911J

ACCIDENT DATE : 02-09-2024 17:40

THIRD PARTY REF. : PROPERTY-POLE

ATTN: MOTOR CLAIMS DEPT.

DATE : 04-09-2024

ESTIMATE COST OF REPAIR TO VEHICLE GBG4911J TOYOTA DYNA

#	QTY	PARTS DESCRIPTION
1	1	FRONT WINDSCREEN GLASS
2	1	FRONT WINDSCREEN RUBBER
3	1	FRONT WINDSCREEN PILLAR LH
4	1	FRONT CORNER PANEL LH
5	1	FRONT CORNER PANEL BRACKET LH
6	1	FRONT GRILLE
7	1	FRONT GRILLE EMBLEM
8	8	FRONT GRILLE CLIP@\$3.50
9	1	FRONT HEADLAMP LH
10	1	FRONT BUMPER
11	1	FRONT BUMPER FOGLAMP COVER LH
12	1	FRONT BUMPER BRACKET@\$125.00
13	1	FRONT STEP GARNISH LH
14	1	FRONT SIDE MIRROR BRACKET LH
15	1	FRONT SIDE MIRROR MOTOR LH
16	1	FRONT SIDE MIRROR ROUND LH
17	1	FRONT SIDE MIRROR SQUARE LH
18	1	FRONT SIDE MIRROR TOP ROUND COVER LH
19	1	FRONT DOOR LH
20	1	FRONT DOOR HINGE TOP LH
21	1	FRONT DOOR HINGE LOWER LH
22	1	FRONT DOOR CHECKER LH
3	1	FRONT DOOR RUBBER FRT LH
4	1	FRONT DOOR RUBBER LH
5	1	FRONT DOOR LOCK LH

AMOUNT (SG\$)

-	650.00	car
-	115.00	alt
-	395.00	X n7
-	135.00	mir
-	55.00	bt
-	230.00	R7
-	35.00	X nn
-	28.00	X n7
-	385.00	car
-	290.00	de
-	55.00	de
125	250.00	bt
-	105.00	cal
-	275.00	bt
-	340.00	dis
-	95.00	mir
-	105.00	car
-	25.00	mir
-	680.00	bt
-	55.00	X
-	55.00	X
-	75.00	X
-	95.00	X
-	115.00	X
-	165.00	X

n7



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBG4911J
ACCIDENT DATE : 02-09-2024 17:40
THIRD PARTY REF. : PROPERTY-POLE

QTY PARTS DESCRIPTION

26	1	AIR CON CONDENSER
27	1	AIR CON FAN ASSY
28	1	AIR CON FAN BRACKET
29	1	FRONT SHOCK ABSORBER LH
30	1	FRONT TOP ARM LH
31	1	FRONT LOWER ARM LH
32	1	FRONT KNUCKLE ARM LH
33	1	FRONT KNUCKLE BEARING INNER LH
34	1	FRONT KNUCKLE BEARING OUTER LH
35	1	FRONT STABILIZER LINK LH
36	1	TIE ROD LH
37	1	TIE ROD END LH
38	1	STEERING RACK AND PINION
39	1	REAR LAMP LH
40	1	FRONT RIM LH
41	1	REAR RIM LH
42	1	REAR SHOCK ABSORBER LH
43	1	REAR BEARING OUTER LH
44	1	REAR BEARING SMALL LH
45	1	REAR SHAFT LH

AMOUNT (SG\$)

550.00	bt
480.00	X
100.00	X
85.00	X
530.00	X
350.00	X
420.00	X
40.00	X
30.00	X
30.00	X
115.00	X
140.00	X
1600.00	X
125.00	aur
300.00	bt
300.00	dd
85.00	X
30.00	X
40.00	X
540.00	X

ADD 10 %
TOTAL (A)

10,698.00

1,069.80

11,767.80

SPECIAL NETT ITEMS

1	1	FRONT DOOR COMPANY PROFILE LH	20.00	ali
2	1	ERP STICKER	20.00	ali
3	1	FRONT NUMBER PLATE	40.00	X nn
4	1	TO FABRICATE AND REPLACE REAR CABIN BOX	10000.00	bt

10040



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9580, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBG4911J
ACCIDENT DATE : 02-09-2024 17:40
THIRD PARTY REF. : PROPERTY-POLE

QTY PARTS DESCRIPTION

TOTAL (C)

AMOUNT (SG\$)

10,080.00

LABOUR CHARGES

1 TO CHECK WIRING SYSTEM

50.00 ✓

2 TO CHECK ALIGNMENT

100.00 80 ✓

3 TO REMOVE/REFIT FRONT WINDSCREEN GLASS

100.00 ✓

4 TO REMOVE/REFIT FRONT UNDERCARRIAGELH

nn 250.00 ~~150~~ ^{plus}

5 TO TRANSFER DOOR MECHANICISM TO NEW DOOR

80.00 60 ✓

6 TO REMOVE/REFIT DASHBOARD

nn 240.00 ~~150~~ ²⁰⁰ ^{plus}

7 TO REMOVE/REFIT/REFILL AIR CON GAS

100.00 ✓

8 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

980.00 800 ✓

9 SPRAYPAINTING CHARGES

880.00 800 -
1990

TOTAL (D)

2,780.00

ESTIMATE TOTAL

24,627.80

Tanglin 97495749 / 62563561

not authorise, Renewt Ex 1600

Tanglin 2111 auto.com 5/9/24 2445pm

L/S after repair
8 days

5181

10040

1990

17211

L/S 13750

8 days

✗