



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMS 767S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BROKEN	\$950.00	\$725.00
1	FRONT BUMPER SIDE RETAINER RH	BROKEN	\$120.00	\$120.00
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	\$150.00	\$0.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	\$585.00	\$0.00
	LESS 25.00% DISCOUNT		(\$451.25)	(\$211.25)
			\$1,353.75	\$633.75
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$45.00	\$30.00
			\$45.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH		\$300.00	\$200.00
	TO UNDERCOATING FOR RUST PROTECTION		\$20.00	\$10.00
	TO WRAPPING ACCIDENT SECTION		\$600.00	\$400.00
			\$920.00	\$610.00
GRAND TOTAL			\$2,318.75	\$1,273.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$1,000.00
Report Ref No: CS/AWA24090097/Eqp3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.