

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS/FCI24090099/Aqp3m4	
	16 RAFFLES QUAY		Date:	11/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3122B	Veh. Inspected	SNJ 1825L	
	Policy No.	-	Coverage	0	
	Claim No.	D24007788MFCT	Excess	\$0.00	
	Assign From	HARMINDER	Assign Date	05/09/2024	
2.	2. Vehicle Details				
	Make & Model	BMW 116I	c.c	1499	
	Engine No.	38226918B38A15A	Year of Reg.	28/12/2022	
	Chassis No.	WBA7K120X07L62689	Colour	RED	
	Odometer	27919 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/45R17	BRIDGESTONE	6	
	L/H Front Tyre	225/45R17	BRIDGESTONE	6	
	R/H Rear Tyre	225/45R17	BRIDGESTONE	6	
	L/H Rear Tyre	225/45R17	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	03/09/2024	Inspection Date	18/09/2024	
	Survey held at	vey held at HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks					
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.RS.					

Estimate Days of Repair