



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNS 4826S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DISTORTED	\$1,550.60	\$887.00
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	\$128.30	\$0.00
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	\$406.80	\$95.00
1	HEADLAMP ASSY LED RH	SCRATCHED	\$2,480.60	\$2,480.60
1	SET FRONT BUMPER CLIPS	NECESSARY	\$80.00	\$40.00
1	HEADLAMP LOWER BRACKET O/S RH	NOT NECESSARY	\$245.60	\$0.00
1	FRONT FENDER LINER RHS	NOT NECESSARY	\$303.60	\$0.00
1	FRONT BUMPER SENSOR	NOT NECESSARY	\$460.30	\$0.00
1	FOG LAMP COVER RH	CRACKED	\$168.60	\$54.00
1	SET FRONT FENDER LINER CLIPS	NOT NECESSARY	\$80.00	\$0.00
1	STEERING TIE ROD RH	NOT NECESSARY	\$328.30	\$0.00
1	STEERING TIE ROD END RH	NOT NECESSARY	\$365.40	\$0.00
1	FRT LOWER ARM RH	NOT NECESSARY	\$1,360.30	\$0.00
1	KNUCKLE ARM RH	NOT NECESSARY	\$1,460.20	\$0.00
1	SHOCK ABSORBER RH	NOT NECESSARY	\$860.30	\$0.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	\$1,095.40	\$0.00
1	WHEEL RIM	NOT NECESSARY	\$1,280.60	\$0.00
1	FRONT BUMPER AIR DUCT RH (ADDITIONAL)	CRACKED	\$328.30	\$223.40
1	FRONT BUMPER MOULDING RH (ADDITIONAL)	CRACKED	\$365.40	\$248.50
	<b>LESS 0.00 / 20.00% DISCOUNT</b>		\$0.00	(\$805.70)
			\$13,348.60	\$3,222.80

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	MISCELLANEOUS ITEM (SN)	NOT NECESSARY	\$60.00	\$0.00
1	ARCYLLIC SEALANT (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$160.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH		\$2,000.00	\$380.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PUTTY, SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS		\$1,800.00	\$400.00
	TO REMOVE AND REINSTALL UNDERCARRIAGE	NOT NECESSARY	\$500.00	\$0.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	NOT NECESSARY	\$150.00	\$0.00
	TO REMOVE AND REINSTALL WIRE HARNESS. CHECK ACCORDING TO DAMAGE		\$200.00	\$20.00
	TO CONDUCT & RESET ECU DIAGNOSTIC PROGRAMME	NOT NECESSARY	\$450.00	\$0.00
	TO RUST PROOF AFFECTED AREA	NOT NECESSARY	\$200.00	\$0.00
	TO CARRY OUT SPRAY COATING	NOT NECESSARY	\$800.00	\$0.00
			\$6,100.00	\$800.00
<b>GRAND TOTAL</b>			<b>\$19,608.60</b>	<b>\$4,022.80</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>\$4,022.80</b>
Report Ref No: CS/FCI24090101/Uqp3				

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.