

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG24090109/AQP3E2
Date: 22/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070067073
Claimant Vehicle No :	GBL9664M	Insured Vehicle No :	GBE8826G
Date of Loss:	02/09/2024	Nature of Claim:	TP
		Claim No:	8948530298SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL9664M	Engine No:	1TR2460286
Make & Model:	TOYOTA HIACE, 2.0 DX (A)	Chassis No:	TRH2000359262
Reg. Date:	23/08/2022 (Man. Year: 2022)	Odometer:	29194 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,983.20	4,849.42	5,133.78	51.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,890.00	1,940.00	50.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,813.20	6,739.42	7,073.78	51.21
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	13,813.20	5,400.00	8,413.20	60.91

INSPECTION

Date of Assignment:	05/09/2024	TSL Auto Pro Selection Pte Ltd (HQ)
Date Inspected:	10/09/2024 Inspected At:	Blk 1 Kaki Bukit Avenue 6, #01-08 Autobay @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	673.10 FL	*673.10 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	94.40 FL	*- FL
3	4		*REAR BUMPER LOWER BRACKET	Not Necessary	72.00 FL	*- FL
4	1		*REAR BUMPER STEP PANEL	Dented	288.50 FL	*288.50 FL
5	1		*REAR END PANEL OUTER	Dented	743.20 FL	*743.20 FL
6	1		*REAR END PANEL INNER	Repair	820.90 FL	*- FL
7	1		*REAR END PANEL TOP METAL STRIPE	Not Necessary	288.50 FL	*- FL
8	2		*REAR END PANEL SIDE EXTENSION	Not Necessary	724.20 FL	*- FL
9	2		*TAILLAMP	Cracked	726.80 FL	*726.80 FL
10	1		*TAILLAMP LOWER APRON	N/S Deformed	172.20 FL	*86.10 FL
11	1		*TAILGATE	Dented	2,239.60 FL	*2,025.00 FL
12	1		*TAILGATE LOCK	Damaged	398.50 FL	*398.50 FL
13	1		*TAILGATE LOCK COVER	Not Necessary	69.50 FL	*- FL
14	1		*TAILGATE LOCK ACTUATOR	Not Necessary	399.10 FL	*- FL
15	1		*TAILGATE WEATHERSTRIPE	Cut	387.30 FL	*387.30 FL
16	2		*TAILGATE DAMPER	Not Necessary	729.10 FL	*- FL
17	2		*TAILGATE HINGE	Not Necessary	152.20 FL	*- FL
18	1		*TAILGATE GLASS MOULDING	Necessary	172.50 FL	*172.50 FL
19	1		*TAILGATE OUTER MOULDING	Not Necessary	298.80 FL	*- FL
20	1		*TAILGATE INNER TRIM COVER	Not Necessary	165.80 FL	*- FL
21	1		*TOYOTA LOGO	Necessary	60.80 FL	*60.80 FL
22	1		*HIACE STICKER	Necessary	65.60 FL	*65.60 FL
23	1		*1250KG STICKER	Necessary	58.50 FL	*58.50 FL
24	1		*SPARE TYRE CARRIAGE	Not Necessary	376.50 FL	*- FL
25	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
26	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
27	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
28	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
29	1		*SET REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*SET TAILGATE OUTER MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
31	1		*SET TAILGATE INNER TRIM COVER CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
33	1		*TAILGATE SURROUND MOULDING	Necessary	200.00 FS	*100.00 FS
34	1		*FLOOR PANEL TOP BOARD	Not Necessary	750.00 FS	*- FS
35	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
36	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
37	1		*8 PAX STICKER	Not Necessary	15.00 FS	*- FS
38	1		*ADVERTISEMENT STICKER	Necessary	350.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,527.60	6,270.90
- List Item Discount on L Items 25.00/25.00% (\$)	2,544.40	1,421.48
Total Parts (\$)	9,983.20	4,849.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	700.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTRY	New	150.00	0.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
9	TO REMOVE INNER FURNITURE	New	500.00	0.00
10	TO REMOVE REAR CAMERA	New	100.00	50.00
Gross Labour Cost (\$)			3,830.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >