

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24090110/UVP3M4  
Date: 11/09/2024

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC24A00031300  
Claimant Vehicle No : SNH3649B Insured Vehicle No : SJV4093X  
Date of Loss: 03/09/2024 Nature of Claim: TP Claim No: DMPC2401160H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNH3649B  
Make & Model: MAZDA 3, 1.5 5DR M-HYBRID ASTINA (A) Engine No: P520642742  
Reg. Date: 13/11/2019 (Man. Year: 2019) Chassis No: JM6BP2HAAK1103256  
Colour: Grey Odometer: 67099 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R18 Rear Tyre Size: 215/45R18  
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm  
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,932.45	1,690.81	1,241.64	42.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	960.00	1,300.00	57.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,192.45	2,650.81	2,541.64	48.95
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	5,192.45	2,100.00	3,092.45	59.56
+ GST 9.00/9.00% (S\$)	467.32	189.00	278.32	59.56
Nett Amount (S\$)	5,659.77	2,289.00	3,370.77	59.56

INSPECTION

Date of Assignment: 05/09/2024  
Date Inspected: 06/09/2024 Inspected At: BLUWEL AUTOMOTIVE SERVICE PTE LTD (HQ)  
1 KAKI BUKIT AVENUE 6, #01-28/53/55/56  
AUTOBAY@KAKI BUKIT  
SINGAPORE 417883  
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2024)
Parts:	143	MAZDA 3 1.5 5DR M-HYBRID ASTINA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH3649B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed/Dented	1,143.51 FL	*1,143.51 FL
2	1		*REAR BUMPER LOWER DIFFUSER	Deformed/Torn	820.00 FL	*820.00 FL
3	1		*REAR BUMPER BEAM	Repair	399.75 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	93.00 FL	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
6	1		*REAR BUMPER PDC SENSOR	Serviceable	250.00 FL	*- FL
7	1		*SET REAR BUMPER PDC SENSOR BRACKETS	Necessary	50.00 FL	*50.00 FL
8	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FL	*50.00 FL
9	1		*REAR END PANEL	Repair	547.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	262.30 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,665.56	2,113.51
- List Item Discount on L Items 20.00/20.00% (\$\$)	733.11	422.70
Total Parts (\$\$)	2,932.45	1,690.81

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR PDC SENSOR	New	80.00	40.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
5	TO SPRAY RUST PROOFING	New	50.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,260.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >