

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090115/RQP3M4**Date:** 08/11/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLU1386C **Insured Vehicle No :** SLH8628C

Date of Loss: 03/09/2024 Nature of Claim: TP Claim No: DMPC2401161H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU1386C**

Make & Model: MAZDA 6, 2.0 Sedan 2.0 Executive I5 (A) Engine No: PE21596479

Reg. Date: 20/04/2021 (Man. Year: 2021) Chassis No: JM6GL1073M0454220

Colour: Grey Odometer: 73328 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,528.64	6,794.83	733.81	9.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,976.00	2,128.00	1,848.00	46.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,504.64	8,922.83	2,581.81	22.44
+ GST 9.00/9.00% (S\$)	1,035.42	803.05	232.37	22.44
Nett Amount (S\$)	12,540.06	9,725.88	2,814.18	22.44

INSPECTION

Date of Assignment: 05/09/2024

Date Inspected: 13/09/2024 Inspected At: Eurokars Supersports Pte Ltd (Tanjong Penjuru)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$209.46 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2024)
Parts:	143	MAZDA 6 2.0 Sedan 2.0 Executive I5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU1386C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FRT BUMPER GL3 W/PS	Deformed	1,177.81 FS	*1,177.81 FS
3	12		*NUT,CLIP	Necessary	28.32 FS	*28.32 FS
4	2		*GROMMET,SCREW	Necessary	4.72 FS	*4.72 FS
5	8		*RIVET,SPLASH SHIELD	Necessary	24.96 FS	*24.96 FS
6	4		*RIVET	Necessary	14.84 FS	*14.84 FS
7	2		*FASTENER	Necessary	4.72 FS	*4.72 FS
8	1		*PROTECTOR(L),BUMPER GL3	Cut	79.23 FS	*79.23 FS
9	1		*COVER LHF BUMPER GL3	* Check	24.87 FS	*- FS
10	1		*CAP(L) GL	Not Necessary	73.00 FS	*- FS
11	2		*SPRING	Not Necessary	18.56 FS	*- FS
12	1		*COVER(L),BUMPER GL3	Not Necessary	36.50 FS	*- FS
13	1		*PLATE(L),SEAL-F.BUMPER GL	Not Necessary	95.25 FS	*- FS
14	1		*RETAINER LHF BUMPER GJ/GL	Not Necessary	14.84 FS	*- FS
15	1		*RETAINER KF	Not Necessary	15.77 FS	*- FS
16	1		*SENSOR,ULTRASONIC	* Check	184.59 FS	*- FS
17	1		*MOULD LHF LWR BUMPER GL3	Cut	303.10 FS	*303.10 FS
18	1		*BRACKET LHF BUMPER GL	Not Necessary	44.76 FS	*- FS
19	1		*PROTECTOR LHF HL GL3	Not Necessary	123.15 FS	*- FS
20	1		*HEADLAMP LH GL IPM 5	Cut	5,137.13 FS	*5,137.13 FS
21	1		*BRACKET LHF HL GL3	Not Necessary	15.77 FS	*- FS
22	1		*BRACKET(L), HEAD LAMP GL3	Not Necessary	37.01 FS	*- FS
23	6		*NUT,CLIP	Not Necessary	19.74 FS	*- FS
Total Parts (\$\$)					7,528.64	6,794.83

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE FRT BUMPER. AND ALL ACCIDENT AFFECTED AREA	New	1,584.00	792.00
2	TO RESPRAY FRT BUMPER	New	1,512.00	756.00
3	TO TRANSFER FRONT SENSORS	New	330.00	180.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	250.00
Gross Labour Cost (\$\$)			3,976.00	2,128.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >