



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNN 9491S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH SIDE MIRROR ASSY	DENTED/CUT	\$8,565.95	\$2,180.00
1	RH SIDE MIRROR COVER	TO REPAIR SEE LABOUR	\$214.75	\$0.00
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	\$1,657.95	\$0.00
1	FRONT RH FENDER INNER SHIELD	SERVICEABLE	\$422.10	\$0.00
1	FRONT RH FENDER INNER GANISH	SERVICEABLE	\$152.70	\$0.00
1	FRONT BUMPER	BUCKLED	\$3,289.80	\$1,593.20
1	FRONT RH HEAD LAMP	MTG CRACKED	\$11,359.20	\$5,765.20
1	FRONT RH HEADL LAMP BRACKET	TO REPAIR SEE LABOUR	\$720.00	\$0.00
1	FRONT BUMPER GRILLE ASSY	SCRATCHED/CUT	\$3,774.00	\$1,830.40
1	FRONT BUMPER GRILLE CHROME MOULDING RH TOP	CUT/SCRATCHED	\$297.95	\$297.95
1	FRONT BUMPER GRILLE CHROME MOULDING RH SIDE	SCRATCHED	\$347.60	\$159.00
1	FRONT BUMPER GRILLE CHROME MOULDING RGH LOW	CUT/SCRATCHED	\$347.60	\$159.00
1	WIPER TANK NECK	SERVICEABLE	\$179.45	\$0.00
1	WIPER TANK	SERVICEABLE	\$424.70	\$0.00
1	FRONT REINFORMENT	TO REPAIR SEE LABOUR	\$980.75	\$0.00
1	FRONT REINFORMENT FOAM	SERVICEABLE	\$288.00	\$0.00
1	FRONT LOWER REINFORMENT	TO REPAIR SEE LABOUR	\$540.05	\$0.00
1	FRONT LOWER REINFORMENT FOAM	SERVICEABLE	\$288.00	\$0.00
1	FRONT RH RETAINER	SERVICEABLE	\$229.05	\$0.00
1	FRONT RH KNUCKLER	SERVICEABLE	\$1,013.15	\$0.00
1	FRONT RH WHEEL BEARING	NOT NECESSARY	\$720.00	\$0.00
1	FRONT RH LOWER ARM	SERVICEABLE	\$651.75	\$0.00
1	FRONT RH ABSORBER	SERVICEABLE	\$993.15	\$0.00
1	FRONT RH FOG LAMP	MTG CRACKED	\$997.50	\$906.80
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$3,222.89)
			\$38,455.15	\$9,668.66

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
6	FRONT BUMPER CLIP @\$8.00 (SN)	NECESSARY	\$48.00	\$48.00
8	FRONT FENDER INNER SHIELD CLIP @\$8.00 (SN)	NOT NECESSARY	\$64.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT PARKING SENSOR @\$280.00 (SN)	SERVICEABLE	\$560.00	\$0.00
1	FRONT RH RIM (SN)	SERVICEABLE	\$800.00	\$0.00
1	FRONT RH TYRES (SN)	SERVICEABLE	\$250.00	\$0.00
			\$1,722.00	\$48.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF RH SIDE MIRROR COVER, FRONT RH FENDER, FRONT RH HEAD LAMP BRACKET, FRONT REINFORMENT AND FRONT LOWER REINFORMENT.		\$1,200.00	\$400.00
	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA		\$900.00	\$500.00
	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	NOT NECESSARY	\$250.00	\$0.00
	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS		\$200.00	\$20.00
	TO SUPPLY LABOUR TO REMOVE AND REFIX UNDERCARRIAGE	NOT NECESSARY	\$250.00	\$0.00
	TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	NOT NECESSARY	\$50.00	\$0.00
	TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT	NOT NECESSARY	\$120.00	\$0.00
	TO SUPPLY COMPUTER TO DIAGNOSTIC & REPROGRAMMING	NOT NECESSARY	\$450.00	\$0.00
			\$3,420.00	\$920.00

GRAND TOTAL			\$43,597.15	\$10,636.66
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$8,500.00
Report Ref No: CS/SMO24090120/Knp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.