

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090121/KNP3M4**Date:** 20/09/2024REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC23A00349300
Claimant Vehicle No : SNN6531E **Insured Vehicle No :** SJR7200E
 Date of Loss: 05/09/2024 Nature of Claim: TP Claim No: DMPC2401170H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNN6531E**
 Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: M15AY813075
 Reg. Date: 20/12/2023 (Man. Year: 2023) Chassis No: MXPL101089887
 Colour: Metallic Pearl White Odometer: 65793 km
 Engine Capacity: 1490 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: TRANSFORCE 9 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: TRANSFORCE 9 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,473.57	3,455.27	3,018.30	46.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,460.00	850.00	36.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,783.57	4,915.27	3,868.30	44.04
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	8,783.57	3,900.00	4,883.57	55.60
+ GST 9.00/9.00% (S\$)	790.52	351.00	439.52	55.60
Nett Amount (S\$)	9,574.09	4,251.00	5,323.09	55.60

INSPECTION

Date of Assignment: 06/09/2024
 Date Inspected: 09/09/2024 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2024)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNN6531E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,358.50 FL	*1,358.50 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	89.50 FL	*89.50 FL
3	1		*REAR TAILGATE TOYOTA EMBLEM	Not Necessary	75.20 FL	*- FL
4	1		*REAR TAILGATE OUTER GARNISH	Serviceable	485.20 FL	*- FL
5	1		*REAR TAILGATE INNER LOCK	Repair	425.50 FL	*- FL
6	1		*REAR TAILGATE INNER RUBBER	Dented/Distorted	381.90 FL	*290.00 FL
7	1		*REAR TAILGATE INNER CARDBOARD	Serviceable	281.50 FL	*- FL
8	1		*REAR TAILGATE INNER HANDLE	Serviceable	121.50 FL	*- FL
9	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	181.50 FL	*181.50 FL
10	1		*REAR LH TAILLAMP	Cut	685.20 FL	*581.50 FL
11	1		*REAR BUMPER	Buckled	1,125.20 FL	*585.00 FL
12	1		*REAR BUMPER SIDE REFLECTOR	N/S Cut	264.20 FL	*95.00 FL
13	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
14	1		*REAR BUMPER TOWING COVER	Serviceable	85.20 FL	*- FL
15	1		*REAR BUMPER CENTRE PARKING SENSOR	Dented/Shorted (1Pc Only)	517.00 FL	*258.50 FL
			2PCS			
16	4		*REAR BUMPER CENTRE PARKING SENSOR BASE	Necessary	342.00 FL	*260.00 FL
17	1		*REAR END PANEL OUTER	Bent	564.20 FL	*564.20 FL
18	1		*REAR END PANEL OUTER SENSOR	Serviceable	281.50 FL	*- FL
19	1		*REAR END PANEL INNER	Repair	781.45 FL	*- FL
20	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	371.85 FL	*250.00 FL
21	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
22	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,588.10	4,593.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,114.53	1,138.43
Total Parts (\$\$)	6,473.57	3,455.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
2	TUFFKOTE	New	80.00	60.00
3	WIRING	New	80.00	20.00
4	SPRAY PAINTING	New	1,000.00	660.00
5	LABOUR CHARGES	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,310.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >