## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 8

#09-04A Singapore Post Centre

Singapore 408600

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 11 Sep 2024

# **Preliminary Advice**

Insured Vehicle No : SJR7200E

 TP Vehicle No
 : SNN6531E
 Accident Date
 : 05/09/2024

 Make
 : ADIVA AD1 200
 Assignment Date
 : 06/09/2024

Date of Inspection : 09/09/2024 Est. Duration of Repair : 4

Inspection At : HUI YANG MOTOR PTE LTD (HQ)

176 SIN MING DRIVE #04-02, SIN MING AUTOCARE

SINGAPORE 575721

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,783.58
Revised Amount	:S\$	3,709.00
Check Items (Estimated)	:S\$	2,223.50
Total	:S\$	5,932.50

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
	have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( x ) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.