4/7/25, 11:01 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090122/KMA3Q2

Date: 07/04/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_03

Claimant Vehicle SHD5965S Insured Vehicle No: SNA6988P

No:

Date of Loss: 17/07/2024 Nature of Claim: TP Claim No: MFL2024D0008874

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD5965S Reg No:

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B63347

01/11/2018 (Man. Year: 2018) Reg. Date: Chassis No: JTDKB3FU703075517

Colour: Metallic Pearl White/Red Odometer: 623833 km

1798 cc **Engine Capacity:** Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: No Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Wanli 8 mm Grenlander 4 mm Front Right Side: Wanli 8 mm Rear Right Side: Grenlander 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,784.34	1,354.03	6,430.31	82.61
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,550.00	1,490.00	3,060.00	67.25
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross 1	Total (S\$)	12,334.34	2,844.03	9,490.31	76.94
Approved Total (Overrid	den) (S\$)		2,300.00		
Nett Amo	ount (S\$)	12,334.34	2,300.00	10,034.34	81.35
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 09/09/2024

Trans-cab Auto Services Pte Ltd Date Inspected: 09/09/2024 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Mar 2025)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD5965S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR LH	Repair	1,641.36 FL	*- FL
2	1		*PANEL SUB-ASSY ,REAR DOOR LH	Bent	1,634.33 FL	*1,634.33 FL
3	1		*FRAME SUB ASSY REAR DOOR OUTSIDE HANDLE LH	Serviceable	243.81 FL	*- FL
4	1		*HANDLE ASSY REAR DOOR OUTSIDE LH	Serviceable	123.06 FL	*- FL
5	1		*WEATHERSTRIP REAR DOOR OPENING TRIM LH	Serviceable	369.60 FL	*- FL
6	1		*HINGE ASSY ,REAR DOOR LOWER LH	Repair	109.62 FL	*- FL
7	1		*HINGE ASSY REAR DOOR UPPER LH	Repair	124.74 FL	*- FL
8	1		*TAPE BLACK OUT NO.1 REAR LH	Necessary	27.62 FL	*27.62 FL
9	1		*TAPE BLACK OUT NO.2 REAR LH	Necessary	44.00 FL	*44.00 FL
10	1		*TAPE BLACK OUT NO.3 REAR LH	Necessary	19.43 FL	*19.43 FL
11	1		*COVER REAR COMBINATION LAMP LH	Serviceable	81.48 FL	*- FL
12	1		*LENS & BODY REAR COMBINATION LAMP LH	Serviceable	559.13 FL	*- FL
13	1		*LENS AND BODY ,REAR LAMP LH	Serviceable	634.73 FL	*- FL
14	1		*COVER REAR BUMPER	Serviceable	558.39 FL	*- FL
15	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	419.90 FL	*- FL
16	1		*GUARD ,REAR BUMPER ,CENTER	Serviceable	726.92 FL	*- FL
17	1		*FILLER ,REAR BUMPER EXTENSION LH	Serviceable	155.72 FL	*- FL
18	1		*SEAL REAR BUMPER SIDE LH	Serviceable	111.41 FL	*- FL
19	1		*RETAINER REAR BUMPER SIDE LH	Serviceable	147.11 FL	*- FL
20	1		*PANEL SUB-ASSY ,QUARTER LH	Repair	1,099.46 FL	*- FL
21	1		*LINER REAR WHEEL HOUSE LH	Serviceable	176.09 FL	*- FL
22	1		*MOULDING ASSY, BODY ROCKER PANEL LH	Repair	624.54 FL	*- FL
23	1		*SET DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
24	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	*- FS
25	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	*60.00 FS
26	1		*REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
27	1		*SET CLIP ,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS
28	1		*SET FENDER CLIP	Not Necessary	130.00 FS	*- FS
29	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	,		
			- List Item Discount on L Items	Sub Total (S\$) s 25.00/25.00% (S\$)	10,192.45 2,408.11	1,785.38 431.35
				Total Parts (S\$)	7,784.34	1,354.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH ,FITTINGS AND OTHER TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING KNOCKING AND STRAIGHTENING THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ADJUST REALIGN THE SAME		1,600.00	500.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	880.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour	Cost (S\$)	4,550.00	1,490.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >