



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24090123/Unp3
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	24/09/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 592E	Veh. Inspected	YR 2144P
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/044 (LK)	Excess	\$0.00
Assign From	LAI PENCHONG	Assign Date	06/09/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2755
Engine No.	1GD9089408	Year of Reg.	15/04/2024
Chassis No.	JHHAGV4620K003897	Colour	WHITE
Odometer	6922 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/75R15	BRIDGESTONE	8
L/H Front Tyre	175/75R15	BRIDGESTONE	8
R/H Rear Tyre	145/80R13	BRIDGESTONE	8
L/H Rear Tyre	145/80R13	BRIDGESTONE	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2024	Inspection Date	09/09/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days