

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090134/XUA3Q2**Date:** 21/11/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : SME6706C **Insured Vehicle No :** SLG2938C
Date of Loss: 05/09/2024 Nature of Claim: TP Claim No: MFL2024D0010678

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME6706C**
Make & Model: KIA CERATO, 1.6 LX (A) Engine No: G4FGJH703413
Reg. Date: 11/10/2018 (Man. Year: 2018) Chassis No: KNAF1416MK5013141
Colour: Metallic Silver Odometer: 119675 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: MARQUIS 8 mm Rear Left Side: Yokohama 3 mm
Front Right Side: MARQUIS 8 mm Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	550.08	550.08	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	900.00	150.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,600.08	1,450.08	150.00	9.37
+ GST 9.00/9.00% (S\$)	144.01	130.51	13.50	9.37
Nett Amount (S\$)	1,744.09	1,580.59	163.50	9.37
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,787.84		

INSPECTION

Date of Assignment: 22/10/2024
Date Inspected: 22/10/2024 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (HQ)
Sector A, Block 21,, Sin Ming Industrial Estate, #01-56/58/60
Singapore 575679
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2025)
Parts:	143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME6706C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	588.00 FL	*588.00 FL
2	4		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	23.20 FL	*23.20 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					611.20	611.20
- List Item Discount on L Items 10.00/10.00% (S\$)					61.12	61.12
Total Parts (S\$)					550.08	550.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR FRONT BUMPER AND RENEW PARTS	New	450.00	350.00
2	TO SPRAY PAINT (INCLUDE BLEND FRONT DOOR RH)	New	600.00	550.00
Gross Labour Cost (\$\$)			1,050.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >