

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090136/KMA3Q2
Date: 18/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900258275
Claimant Vehicle No :	SNG5671C	Insured Vehicle No :	SMR657G
Date of Loss:	05/09/2024	Nature of Claim:	TP
		Claim No:	1950524275SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG5671C	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 RWD, (A)	Chassis No:	LRW3F7FS2NC601751
Reg. Date:	18/08/2022 (Man. Year: 2022)	Odometer:	27135 km
Colour:	Metallic Pearl White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,207.80	3,235.86	1,971.94	37.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	990.00	1,280.00	56.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,477.80	4,225.86	3,251.94	43.49
+ GST 9.00/9.00% (S\$)	673.00	380.33	292.67	43.49
Nett Amount (S\$)	8,150.80	4,606.19	3,544.61	43.49
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		5,039.37		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment:	09/09/2024	
Date Inspected:	09/09/2024 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	766.00 FL	*766.00 FL
2	1		*FRONT RH BUMPER RETAINER	Necessary	1.86 FL	*1.86 FL
3	1		*FRONT RH BUMPER SIDE SUPPORT BRACKET	Cracked	12.14 FL	*12.14 FL
4	1		*FRONT RH BUMPER FOG LAMP COVER	Scratched	6.54 FL	*6.54 FL
5	1		*FRONT PARKING SENSOR	Shorted	163.55 FL	*163.55 FL
6	1		*FRONT BUMPER LOWER	Serviceable	186.91 FL	*- FL
7	1		*FRONT BUMPER ENERGY ABSORBER	Serviceable	46.72 FL	*- FL
8	1		*FRONT RH FENDER PANEL	Buckled	448.60 FL	*448.60 FL
9	1		*FRONT RH FENDER LINER	Cracked	116.82 FL	*116.82 FL
10	1		*FRONT RH HEADLAMP	Mtg Cracked	1,741.00 FL	*1,741.00 FL
11	1		*FRONT RH WHEEL RIM COVER	Serviceable	32.40 FL	*- FL
12	1		*FRONT RH WHEEL RIM	Serviceable	505.00 FL	*- FL
13	1		*FRONT RH KNUCKLE ARM	Serviceable	420.56 FL	*- FL
14	1		*FRONT RH KNUCKLE HUB+BEARING	Not Necessary	233.64 FL	*- FL
15	1		*FRONT RH LOWER ARM -STRAIGHT	Serviceable	242.99 FL	*- FL
16	1		*FRONT RH LOWER ARM -CURVED	Serviceable	224.29 FL	*- FL
17	1		*FRONT RH UPPER ARM	Serviceable	121.49 FL	*- FL
18	1		*FRONT RH STEERING TIE ROD END	Serviceable	121.49 FL	*- FL
19	1		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
20	1		*FRONT BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*FRONT FENDER LINER CLIPS	Necessary	50.00 FS	*50.00 FS
22	1		*SET FRONT PARKING SENSOR MOUNTING BRACKET	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,747.00	3,561.51
- List Item Discount on L Items 10.00/10.00% (\$)	539.20	325.65
Total Parts (\$)	5,207.80	3,235.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE REPLACE REFIX REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER FRONT RH FENDER ETC	New	650.00	440.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR & ETC	New	100.00	60.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	30.00
5	TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	300.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	20.00
7	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	120.00	0.00
8	TO R&R TYRE RIM	New	100.00	0.00
9	TO READJUST AND REALIGN HEADLAMP AIM	New	100.00	40.00
			Gross Labour Cost (\$)	2,270.00
				990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >