

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090140/AMA3Q2**Date:** 14/05/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000047
Claimant Vehicle No : SMN4281B **Insured Vehicle No :** SLA2947H
 Date of Loss: 23/08/2024 Nature of Claim: TP Claim No: 1175211014SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN4281B**
 Make & Model: TOYOTA LAND CRUISER, 4.6 AX (A) Engine No: 1UR0786878
 Reg. Date: 08/08/2019 (Man. Year: 2019) Chassis No: URJ2024187615
 Colour: Black Odometer: 47197 km
 Engine Capacity: 4608 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/60 R18 Rear Tyre Size: 285/60 R18
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,785.45	6,784.50	10,000.95	59.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,340.00	2,340.00	63.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,465.45	8,124.50	12,340.95	60.30
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	20,465.45	6,500.00	13,965.45	68.24
+ Loss of Use (5.0 x S\$110.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		7,108.25		
Global Sum Settlement (S\$)		7,100.00		

INSPECTION

Date of Assignment: 28/08/2024
 Date Inspected: 28/08/2024 Inspected At: YSK Auto Workshop (HQ)
 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,850.60 FL	*2,450.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	157.00 FL	*- FL
3	1		*REAR BUMPER TOP PAD	Deformed	298.20 FL	*298.20 FL
4	1		*REAR BUMPER LAMP	O/S Cracked	514.80 FL	*257.40 FL
5	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	1,208.80 FL	*604.40 FL
6	1		*REAR BUMPER BEAM	Dented	180.90 FL	*180.90 FL
7	1		*REAR BUMPER CENTRE GUIDE	Cracked	254.50 FL	*254.50 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	531.50 FL	*- FL
9	1		*TAILLAMP	O/S Cracked	2,562.20 FL	*1,110.00 FL
10	1		*TAILGATE (UPPER)	Repair	3,501.70 FL	*- FL
11	1		*TAILGATE (UPPER) LOCK	Not Necessary	382.90 FL	*- FL
12	1		*TAILGATE (UPPER) CHROME MOULDING	Not Necessary	518.50 FL	*- FL
13	2		*TAILGATE (UPPER) REFLECTOR	Not Necessary	2,160.80 FL	*- FL
14	1		*TAILGATE (UPPER) SPOILER	Repair	1,645.60 FL	*- FL
15	1		*REAR (UPPER) GLASS MOULDING	Not Necessary	187.90 FL	*- FL
16	1		*TOYOTA LOGO	Necessary	85.80 FL	*85.80 FL
17	1		*TAILGATE (LOWER)	Dented	3,488.20 FL	*3,210.00 FL
18	1		*V8 EMBLEM	Necessary	78.40 FL	*78.40 FL
19	1		*UTILITY TRAY	Deformed	396.40 FL	*396.40 FL
20	1		*REAR END PANEL	Repair	1,055.90 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
23	1		*SET TAILGATE (UPPER) CHROME MOULDING CLIPS	Not Necessary	30.00 FS	*- FS
24	1		*TAILGATE (UPPER) SPOILER SEALANT	Necessary	60.00 FS	*60.00 FS
25	1		*TAILGATE (UPPER) GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,300.60	9,016.00
- List Item Discount on L Items 25.00/25.00% (\$)	5,515.15	2,231.50
Total Parts (\$)	16,785.45	6,784.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,400.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	30.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVER EAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	0.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	0.00
Gross Labour Cost (\$\$)			3,680.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >