

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24090141/UNP3M4**Date:** 14/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002092690		
<b>Claimant Vehicle No :</b>	SFM13Z	<b>Insured Vehicle No :</b>	FBG7340L		
Date of Loss:	22/08/2024	Nature of Claim:	TP	Claim No:	371573

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SFM13Z</b>	Engine No:	2AR1301824
Make & Model:	TOYOTA LEXUS, 2.5 ES300H CVT (A)	Chassis No:	JTHBW1GG002098255
Reg. Date:	18/06/2015 (Man. Year: 2015)	Odometer:	156688 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55ZR17	Rear Tyre Size:	225/55ZR17
Front Left Side:	GREENTRAC 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	GREENTRAC 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,384.99	6,036.79	14,348.20	70.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	790.00	2,560.00	76.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,734.99</b>	<b>6,826.79</b>	<b>16,908.20</b>	<b>71.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>23,734.99</b>	<b>5,400.00</b>	<b>18,334.99</b>	<b>77.25</b>

**INSPECTION**

Date of Assignment:	09/09/2024	53 UBI AVE 1, #01-23 SINGAPORE 408934 REPAIRER: TECHNO AUTOMOTIVE PRIVATE LIMITED
Date Inspected:	10/09/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	143	TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFM13Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut/Twisted	1,359.00 FN	*1,359.00 FN
2	1		*FRONT BUMPER SIDE RETAINER	Serviceable	114.00 FN	*- FN
3	1		*HEADLAMP HID LH	Cracked	6,854.00 FN	*4,178.50 FN
4	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	215.00 FN	*- FN
5	1		*FRONT FENDER LH	Dented/Bent	1,125.60 FN	*1,125.60 FN
6	1		*FRONT FENDER COWLING LH	Serviceable	285.00 FN	*- FN
7	1		*FRONT SHOCK ABSORBER LH	Not Necessary	765.00 FN	*- FN
8	1		*FRONT UPPER ARM LH	Not Necessary	665.00 FN	*- FN
9	1		*FRNT LOWER ARM LH	Not Necessary	691.50 FN	*- FN
10	1		*FRONT KNUCKLE ARM V	Not Necessary	1,445.00 FN	*- FN
11	1		*FRONT STEERING RACK AND PINION	Not Necessary	4,874.00 FN	*- FN
12	1		*FRONT WHEEL HUP WITH BEARING LH	Not Necessary	694.00 FN	*- FN
13	1		*FRONT WHEEL RIM LH	Repair	2,514.00 FN	*- FN
14	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FS	*40.00 FS
15	1		*FRONT FENDER COWLING CLIPS LH	Not Necessary	39.00 FS	*- FS
16	1		*FRONT WHEEL TYRE RH	Serviceable	680.00 FS	*- FS
17	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
18	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	22,545.10	6,703.10
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	2,160.11	666.31
Total Parts (\$\$)	20,384.99	6,036.79

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OFF AND REPLACE REAR RHS FENDER. RESTRUCTURE CENTER CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	New	1,200.00	300.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,200.00	400.00
3	DISMANTLE AND REPLACE FRONT UNDER-CARRIAGE COMPONENTS	New	300.00	0.00
4	APPLY TUFF COATING TREATMENT	New	100.00	30.00
5	PERFORM DIAGNOSTIC CHECK	New	300.00	0.00
6	WHEEL ALIGNMENT	New	250.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,350.00</b>	<b>790.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >