Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Crystabelle Tan Date: 10 Sep 2024

Preliminary Advice

Vehicle No : SNG5537H Accident Date : 30/08/2024

Make : AUDI A6 Policy No. : MPC23P00213400

Assignment Date : 09/09/2024 Excess : \$\$0.00 Date of Inspection : 10/09/2024 Est. Duration of Repair : 4

Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)

BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A

SINGAPORE 768761

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,858.00
Revised Amount	:S\$	12,758.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,758.00
Total	:S\$	12,758.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

 Pre-Accident Value
 :S\$ 43,000.00

 COE / PARF Rebate
 :S\$ 30,889.00

Salvage Value :S\$

Margin for Repair :S\$ 12,111.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : REPAIRER UNABLE TO LOCATE THE 2ND HAND PARTS AND REQUEST LUMP SUM -10% INSTEAD OF 20%.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.