

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 03/09/2024

07/09/2024

TP 1st Cap
Hui Rong

Estimated repair cost for vehicle no: SNN8093P MERCEDES BENZ CLA 200 (R18 BI)

CHASSIS: WDD1173432N060157 (2013)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Delud</i>	\$1,798.00	\$1,798.00 <i>1690</i>
2	1	FRONT BUMPER REINFORCEMENT <i>re new</i>	\$608.00	\$608.00 <i>+</i>
3	1	FRONT BUMPER SPONGE <i>cracked</i>	\$212.00	\$212.00 <i>+</i>
4	1	FRONT BUMPER SIDE RETAINER LH <i>re new</i>	\$127.00	\$127.00 <i>+</i>
5	1	FRONT BUMPER FOG LAMP COVER LH <i>cr</i>	\$167.00	\$167.00 <i>-</i>
6	1	FRONT BUMPER FOG LAMP COVER SENSOR LH <i>re new</i>	\$321.00	\$321.00 <i>+</i>
7	1	FRONT BUMPER CENTER SENSOR COVER LH <i>Delud</i>	\$124.00	\$124.00 <i>+</i>
8	1	FRONT BUMPER CENTER SENSOR LH <i>Delud</i>	\$321.00	\$321.00 <i>-</i>
9	1	FRONT BUMPER SIDE BRACKET LH <i>cracked</i>	\$211.00	\$211.00 <i>+</i>
10	1	FRONT GRILLE <i>re new</i>	\$845.00	\$845.00 <i>+</i>
11	1	FRONT GRILLE LOGO <i>re new</i>	\$95.00	\$95.00 <i>+</i>
12	1	LH FRONT HEADLAMP <i>Cap</i>	\$4,359.00	\$4,359.00 <i>3240</i>
13	1	LH FRONT HEADLAMP LOWER BRACKET LH <i>re new</i>	\$159.00	\$159.00 <i>+</i>
14	1	LH FRONT HEADLAMP BALAST UNIT <i>Demoged</i>	\$894.00	\$894.00 <i>+</i>
15	1	LH FRONT HEADLAMP LED CONTROL UNIT <i>re new</i>	\$563.00	\$563.00 <i>+</i>
16	1	LH FRONT FENDER <i>re new</i>	\$697.00	\$697.00 <i>+</i>
17	1	LH FRONT FENDER INNER SHIELD RH <i>turn</i>	\$254.00	\$254.00 <i>+</i>

TOTAL : \$11,755.00

LESS 10 % \$1,175.50

SUB-TOTAL : \$10,579.50

7113
6401.70

SNN8093P MERCEDES BENZ

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	LH FRONT HEADLAMP CLIPS <i>new</i>	\$25.00	\$25.00 +
2	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 50
3	1	LH FRONT FENDER INNER SHIELD CLIPS <i>new</i>	\$120.00	\$120.00 +

50

TOTAL: \$225.00

TOTAL PARTS \$10,804.50

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,400.00	400
2	LABOUR FOR SPRAYPAINTING	\$1,200.00	300
3	WIRING CHECK	\$80.00	30
4	TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS	\$300.00	+
5	TO RESET/RE-PROGRAMME FRONT BUMPER SENSOR / WARNING LIGHT ON	\$300.00	200

930

Subtotal :- \$3,280.00

Total:- \$14,084.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
2/s 09/09/24

04 Rep ~~03 Reps~~
Supplementary: 1106-10
to be: 8487-80

C/s: 6.8K

6.8K

SM INTEGRATED PTE LTD

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_INTEGRATED@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

UEN: 202235196G

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 03/09/2024

Estimated repair cost for vehicle no: SNN8093P MERCEDES BENZ CLA 200 (R18 BI)

CHASSIS: WDD1173432N060157 (2013)

SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER UNDER COVER <i>torn</i>	\$178.00	\$178.00 ✓
2	1	FRONT BUMPER LOWER LIP <i>LH</i> <i>cracked</i>	\$780.00	\$780.00 450
3	1	FRONT BUMPER LOWER LIP INNER BRACKET LH <i>broken</i>	\$320.00	\$320.00 +
4	1	FRONT BUMPER FOG LAMP SUPPORT GARNISH LH <i>cracked</i>	\$121.00	\$121.00 ✓

Front Bumper lower Grille

480 /

cracked

TOTAL : \$1,399.00

LESS 10 % \$139.90

SUB-TOTAL : \$1,259.10

1229

Supplementary: 1106.10