

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24060151/KQP3E2
Date: 11/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003356639
Claimant Vehicle No :	SLB7964U	Insured Vehicle No :	SLT9920M
Date of Loss:	19/05/2024	Nature of Claim:	TP
		Claim No:	360536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7964U	Engine No:	3ZRB718012
Make & Model:	TOYOTA HARRIER, 2.0 PREMIUM CVT (A)	Chassis No:	ZSU600070891
Reg. Date:	22/04/2016 (Man. Year: 2015)	Odometer:	184060 km
Colour:	Metallic Maroon		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,304.77	45.00	12,259.77	99.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	270.00	2,300.00	89.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,874.77	315.00	14,559.77	97.88
+ GST 9.00/9.00% (S\$)	1,338.73	28.35	1,310.38	97.88
Nett Amount (S\$)	16,213.50	343.35	15,870.15	97.88

INSPECTION

Date of Assignment:	19/06/2024	
Date Inspected:	30/09/2024	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2024)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 PREMIUM CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7964U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE ASSY	Serviceable	911.00 FL	*- FL
2	1		*FRONT BUMPER	Repair	934.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	143.20 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	143.20 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Serviceable	369.20 FL	*- FL
6	1		*FRONT BUMPER LOWER LIP	Serviceable	402.70 FL	*- FL
7	2		*TOWING COVER	Serviceable	68.60 FL	*- FL
8	1		*FRONT LH HEADLAMP	Serviceable	2,196.50 FL	*- FL
9	1		*FRONT LH HEADLAMP LOWER BRACKET	Repair	87.10 FL	*- FL
10	1		*FRONT RH HEADLAMP	Serviceable	2,196.50 FL	*- FL
11	1		*FRONT RH HEADLAMP LOWER BRACKET	Repair	87.10 FL	*- FL
12	1		*FRONT REINFORCEMENT BAR	Repair	644.20 FL	*- FL
13	1		*FRONT LOCK BRACE PANEL / BRACKET	Repair	311.80 FL	*- FL
14	1		*FRONT RADIATOR TOP GARNISH	Serviceable	448.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Repair	1,243.90 FL	*- FL
16	1		*AIRCON CONDENSOR	Serviceable	2,368.10 FL	*- FL
17	1		*RADIATOR	Serviceable	3,394.10 FL	*- FL
18	1		*NUMBER PLATE GARNISH	No such part	230.00 FL	*- FL
19	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
20	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*SET FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*45.00 FS
22	1		*SET FRONT RADIATOR TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,349.70	45.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,044.93	0.00
Total Parts (\$\$)	12,304.77	45.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	220.00
2	LABOUR REMOVE / REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	50.00
3	TO CHECK WIRING SYSTEM	New	100.00	0.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
5	TO REMOVE / REFIX / REPLACE RADIATOR COWLING ASSY, AIRCON CONDENSOR (PIPING, HOSE, TOP UP AIRCON GAS, REFILL COOLANT & ETC	New	350.00	0.00
Gross Labour Cost (S\$)			2,570.00	270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >