



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMP 8543J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	R/R FENDER	BADLY DENTED	\$1,500.00	\$1,120.00
1	REAR BUMPER	CUT	\$780.00	\$680.00
1	R/R TAILLAMP	CRACKED	\$680.00	\$580.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$476.00)
			\$2,960.00	\$1,904.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR REMOVING CUTTING R/R FENDER OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS & ALSO TO REPAIR R/R DOOR		\$1,200.00	\$600.00
	TO RESPRAY R/R FENDER, REAR BUMPER & R/R DOOR		\$1,200.00	\$600.00
	TO REMOVE AND INSTALL REAR QUARTER GLASS		\$150.00	\$50.00
	TO REMOVE FUEL TANK ASSY OUT TO FACILITATE REPAIR		\$300.00	\$50.00
			\$2,850.00	\$1,300.00

<b>GRAND TOTAL</b>	<b>\$5,810.00</b>	<b>\$3,204.00</b>
--------------------	-------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$2,500.00</b>
---	--	-------------------

Report Ref No: CS/LIP24090154/Unh3

MARKET VALUE: \$70,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$31,324.00=NETT VALUE: \$38,676.00

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.