

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24004674/ANP3M4

Date: 06/08/2024

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBH7652G	Insured Vehicle No :	SMH4420Z
Date of Loss:	03/06/2024	Nature of Claim:	TP
		Claim No:	DMPU2400015H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH7652G		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)	Engine No:	1KD2827080
Reg. Date:	27/09/2018 (Man. Year: 2018)	Chassis No:	JTFHT02P500245260
Colour:	Silver	Odometer:	168117 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,679.87	10,846.37	12,833.50	54.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,220.00	2,990.00	4,230.00	58.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,899.87	13,836.37	17,063.50	55.22
Approved Total (Overridden) (S\$)		11,000.00		
Nett Amount (S\$)	30,899.87	11,000.00	19,899.87	64.40

INSPECTION

Date of Assignment:	04/06/2024	
Date Inspected:	05/06/2024	Inspected At: KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020 SINGAPORE 489978
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Aug 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH7652G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,125.80 FL	*2,125.80 FL
2	1		*TAILGATE BADGE	Necessary	95.20 FL	*95.20 FL
3	1		*TAILGATE OUTER GARNISH	Not Necessary	245.60 FL	*- FL
4	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
5	1		*TAILGATE INNER LOCK	Not Necessary	461.60 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Necessary	56.00 FL	*- FL
7	1		*TAILGATE INNERTRIM	Not Necessary	298.70 FL	*- FL
8	1		*SET TAILGATE INNERTRIM CLIPS	Not Necessary	30.00 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	381.90 FL	*- FL
10	2		*TAILGATE SIDE STOPPER (MALE)	Not Necessary	72.00 FL	*- FL
11	2		*TAILGATE SIDE STOPPER (FEMALE)	Not Necessary	78.00 FL	*- FL
12	2		*TAILGATE ABSORBER	Not Necessary	491.20 FL	*- FL
13	1		*TAILGATE WINDSCREEN MOLDING	Necessary	145.80 FL	*145.80 FL
14	1		*SET TAILGATE WINDSCREEN INNER SEAL	Necessary	70.00 FL	*70.00 FL
15	1		*TAILLAMPS	N/S Cracked	651.20 FL	*325.60 FL
16	2		*TAILLAMPS INNER SEALER	Not Necessary	60.00 FL	*- FL
17	1		*TAILLAMPS PANEL LH	Repair	498.50 FL	*- FL
18	2		*SET TAILLAMPS CLIPS	Necessary	50.00 FL	*10.00 FL
19	1		*REAR BUMPER	Distorted	472.50 FL	*472.50 FL
20	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked	138.40 FL	*69.20 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
22	1		*REAR CORNER BUMPER	N/S Distorted	251.20 FL	*125.60 FL
23	1		*REAR CORNER BUMPER RETAINER	N/S Distorted	104.60 FL	*52.30 FL
24	2		*SET REAR CORNER BUMPER CLIPS	Necessary	40.00 FL	*10.00 FL
25	1		*END PANEL (INNER)	Repair	895.60 FL	*- FL
26	1		*END PANEL (OUTER)	Distorted	605.20 FL	*605.20 FL
27	1		*END PANEL TOP PLATE	Not Necessary	245.60 FL	*- FL
28	1		*REAR FENDER LH	Distorted	1,875.60 FL	*1,875.60 FL
29	1		*REAR FENDER INNER LH	Repair	1,985.30 FL	*- FL
30	1		*REAR FENDER INNER TRIM LH	Not Necessary	298.60 FL	*- FL
31	1		*REAR FENDER AIRDUCT LH	Cracked	65.30 FL	*65.30 FL
32	1		*REAR MUDFLAP LH	Not Necessary	89.20 FL	*- FL
33	1		*FLOOR PANEL (BEHIND PORTION)	Repair	2,045.30 FL	*- FL
34	1		*FRONT BONNET	Not Necessary	658.90 FL	*- FL
35	1		*FRONT BONNET LOGO	Not Necessary	95.20 FL	*- FL
36	1		*FRONT BONNET INNER LOCK	Not Necessary	298.60 FL	*- FL
37	1		*FRONT CORNER PANEL RH	Not Necessary	451.20 FL	*- FL
38	2		*HEADLAMPS	Cracked	1,677.00 FL	*1,677.00 FL
39	2		*SET HEADLAMPS CLIPS	Not Necessary	60.00 FL	*- FL
40	1		*AIR FILTER BOX	Not Necessary	1,022.40 FL	*- FL
41	1		*FRONT BUMPER	Deformed	625.30 FL	*625.30 FL
42	1		*FRONT BUMPER CENTRE LOWER COVER	Not Necessary	165.30 FL	*- FL
43	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	290.60 FL	*- FL
44	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
45	1		*FRONT BUMPER TOP BEAM	Dented	379.80 FL	*379.80 FL
46	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	208.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER REINFORCEMENT	Dented	424.00 FL	*424.00 FL
48	2		*FRONT BUMPER REINFORCEMENT SIDE BRACKET	Not Necessary	276.00 FL	*- FL
49	2		*FRONT BUMPER TOWING COVERS	Not Necessary	71.20 FL	*- FL
50	1		*FRONT GRILLE BASE	Cracked	568.90 FL	*568.90 FL
51	1		*FRONT GRILLE OUTER GARNISH (TOP)	Cut	298.60 FL	*298.60 FL
52	1		*FRONT GRILLE OUTER GARNISH (BOTTOM)	Cracked	387.50 FL	*387.50 FL
53	2		*FRONT BUMPER FOGLAMP COVERS	Not Necessary	191.60 FL	*- FL
54	1		*FRONT FOG LAMP GARNISH RH	Not Necessary	89.20 FL	*- FL
55	1		*INTERCOOLER	Dented	1,690.20 FL	*1,690.20 FL
56	1		*AIR CON CONDENSER	Dented	1,430.90 FL	*1,430.90 FL
57	1		*RADIATOR BRACE PANEL	Bent	298.20 FL	*298.20 FL
58	1		*RADIATOR (BIG)	Not Necessary	1,356.20 FL	*- FL
59	1		*RADIATOR (SMALL)	Not Necessary	856.90 FL	*- FL
60	1		*TAILGATE STICKER 70KM/H	Necessary	20.00 FS	*10.00 FS
61	1		*TAILGATE TOYOTA HIACE STICKER	Necessary	45.00 FS	*30.00 FS
62	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
63	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
64	1		*SET FLOOR PANEL VINYL MAT	Not Necessary	380.00 FS	*- FS
65	1		*SET REAR FLOOR PANEL WOODEN BOARD	Not Necessary	700.00 FS	*- FS
66	1		*SET REAR FLOOR INSULATOR SEAL	Not Necessary	150.00 FS	*- FS
67	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
68	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
69	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*30.00 FS
70	1		*SET R134A GAS	Necessary	80.00 FS	*40.00 FS
71	1		*SET RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **30,911.50** **14,318.50**

- List Item Discount on L Items 25.00/25.00% (\$\$) 7,231.63 3,472.13

Total Parts (\$\$) **23,679.87** **10,846.37**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,000.00	1,300.00
2	SPRAY PAINTING	New	2,800.00	1,200.00
3	CHECK WIRING ON HEADLAMP	New	120.00	30.00
4	ANTI RUST	New	80.00	80.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL WOODEN BOARD	New	120.00	0.00
7	REMOVE AND INSTALL CONDENSER /TOP UP GAS	New	100.00	60.00
8	REMOVE AND INSTALL TAILGATE PARTS	New	120.00	60.00
9	REMOVE AND INTERIOR UPHOLSTERY	New	150.00	60.00
10	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
11	REPAIR AND REALIGN CHASSIS MEMBER	New	350.00	0.00
12	CHECK WIRING ON TAILAMPS	New	120.00	30.00
Gross Labour Cost (\$\$)			7,220.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >