

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24060152/EQP3M4**Date:** 06/08/2024REFERENCE

Insured/Claimant: FOK YAN HO Policy No: MPC23B00080400
Date of Loss: 13/06/2024 Nature of Claim: OD Claim No: DMPC2400737H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT425K**
Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGHH682294
Reg. Date: 16/10/2017 (Man. Year: 2017) Chassis No: KNAFX411MJ5747136
Colour: Blue Odometer: 152298 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,706.10	1,257.30	448.80	26.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	930.00	330.00	26.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,966.10	2,187.30	778.80	26.26
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	2,966.10	1,750.00	1,216.10	41.00
+ GST 9.00/9.00% (S\$)	266.95	157.50	109.45	41.00
Nett Amount (S\$)	3,233.05	1,907.50	1,325.55	41.00

INSPECTION

Date of Assignment: 19/06/2024 Present Location: Dickson Auto Care Centre Pte Ltd (HQ)
Date Inspected: 27/06/2024 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)
Estimated Period of Repair: 3.0 days 29 Ubi Road 4, Dickson Auto Centre
Singapore 408619

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2024)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT425K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	REPAIR	Bonnet (NPA)	Repair	-	*- F
2	1		Bumper air grille center, front (WCP)	Broken	165.00 F	*165.00 F
3	1		Bumper reinforcement, front (WCP)	Not Necessary	185.00 F	*- F
4	1		Bumper, front (WCP)	Broken	260.00 F	*260.00 F
5	1		Fender RH, front (WCP)	Repair	110.00 F	*- F
6	1		Headlamp RH (WCP)	Cut	650.00 F	*650.00 F
7	1		Number plate bracket LH, front (WCP)	Not Necessary	45.00 F	*- F
8	1		*FRONT BUMPER TOWING COVER (WCP)	Crushed	8.00 F	*8.00 F
9	1		*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
10	1		*FRONT BUMPER SPONGE (WCP)	Not Necessary	45.00 F	*- F
11	1		*FRONT BUMPER SIDE RETAINER LH & RH (WCP)	Broken	20.00 F	*20.00 F
12	1		*FRONT BUMPER LOGO (WCP)	Necessary	25.00 F	*25.00 F
13	1		*FRONT BONNET - REPAIR (NPA)	Repair	-	*- F
14	1		Number plate garnish, rear (WCP)	Not Necessary	23.00 F	*- F

F=Franchise part.

Sub Total (S\$)	1,551.00	1,143.00
+ Margin on L,N Items 10.00/10.00% (S\$)	155.10	114.30
Total Parts (S\$)	1,706.10	1,257.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT HEADLAMP & REFOCUS	New	60.00	30.00
2	TO PROVIDE LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS	New	600.00	300.00
3	TO PROVIDE LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	New	600.00	600.00
Gross Labour Cost (\$\$)			1,260.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >