

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090160/RUA3Q2**Date:** 05/12/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002571_01
Claimant Vehicle No :	SKT9876U	Insured Vehicle No :	SLJ1287M
Date of Loss:	10/09/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9876U		
Make & Model:	BMW X1 SDRIVE18I, 1.5 LED NAV (A)	Engine No:	39485593B38A15A
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	WBAJG12000EN52844
Colour:	Grey	Odometer:	95135 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,720.70	1,811.15	1,909.55	51.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,242.00	425.00	15.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,387.70	4,053.15	2,334.55	36.55
+ GST 9.00/9.00% (S\$)	574.89	364.78	210.11	36.55
Nett Amount (S\$)	6,962.59	4,417.93	2,544.66	36.55
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
Nett Liability (S\$)		4,567.93		

INSPECTION

Date of Assignment:	23/09/2024		
Date Inspected:	23/09/2024	Inspected At:	Performance Motors Limited (HQ) 303 Alexandra Road, Singapore Singapore 159941
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9876U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*RR BUMPER CARRIER	Not Necessary	561.20 FS	*- FS
3	1		*MOUNTING SMART OPENER	Not Necessary	86.70 FS	*- FS
4	1		*REAR TRIM UNDERRIDE PROTECTION (X L)	Scratched	168.75 FS	*168.75 FS
5	1		*ABRASION GUA	Not Necessary	2.90 FS	*- FS
6	1		*ABRASION GUA	Not Necessary	2.90 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED	Deformed	964.30 FS	*964.30 FS
8	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Scratched	283.55 FS	*283.55 FS
9	1		*REAR BUMPER TRIM BOTTOM (LINES)	Scratched	299.55 FS	*299.55 FS
10	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	40.85 FS	*- FS
11	1		*CLIP (26 PCS)	Not Necessary	32.50 FS	*- FS
12	4		*ULTRASONIC SENSOR BLACK	Not Necessary	1,078.60 FS	*- FS
13	6		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	33.90 FS	*- FS
14	10		*EXPANDING RIVET BLACK	Necessary	15.00 FS	*15.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,720.70	1,811.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE PDC ASSEMBLY ,REPLACE DAMAGED PARTS INCLUDE RECONNECTING TO BUMPER AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	177.00	177.00
2	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC AND CARRYOUT NECESSARY REPAIRING WORK ON ACCIDENT DAMAGE AREA	New	1,275.00	850.00
3	PAINTING REAR BUMPER	New	1,038.00	1,038.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	177.00
Gross Labour Cost (\$\$)			2,667.00	2,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >