



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 6886X (SKG 9381Z)

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$1,509.70	\$1,238.00
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	\$81.30	\$0.00
1	REAR BUMPER RH SIDE RETAINER	NOT NECESSARY	\$71.30	\$0.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	\$31.10	\$0.00
1	REAR RH KNUCKLE ARM	DAMAGED	\$1,592.30	\$1,310.00
1	REAR RH KNUCKLE ARM BEARING	DAMAGED	\$870.80	\$750.00
1	REAR RH LOWER ARM	NOT NECESSARY	\$809.70	\$0.00
1	REAR RH SHOCK ABSORBER	NOT NECESSARY	\$1,303.20	\$0.00
1	REAR RH TIE ROD END	NOT NECESSARY	\$130.90	\$0.00
1	REAR RH FENDER MUDFLAP BRACKET (ADDITIONAL)	CRACKED	\$140.60	\$140.60
1	REAR BUMPER RH LOWER BRACKET (ADDITIONAL)	DAMAGED	\$102.30	\$102.30
	LESS 10.00% DISCOUNT		(\$664.32)	(\$354.09)
			\$5,978.88	\$3,186.81

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RH SPORT RIM (SN)	CUT	\$4,219.47	\$1,500.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	\$280.00	\$0.00
1	REAR RH TYRE (SN)	NOT NECESSARY	\$400.00	\$0.00
			\$4,949.47	\$1,530.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR		\$80.00	\$80.00
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC		\$240.00	\$120.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$600.00	\$200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	NOT NECESSARY	\$600.00	\$200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$60.00	\$0.00
			\$1,680.00	\$680.00
GRAND TOTAL			\$12,608.35	\$5,396.81
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$4,300.00
Report Ref No: CS/INC24090162/Aqh3m4				

TOTAL FOR SPARE PARTS: \$10,928.35 \$ 4,716.81
TOTAL FOR LABOUR : \$ 1,680.00 \$ 680.00
TOTAL REPAIR COST: \$12,608.35 \$ 5,396.81

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.