



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLR 5449U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	ENGINE OIL SUMP	DENTED	\$371.30	\$371.30
1	FRONT BUMPER	DEFORMED	\$1,643.50	\$1,295.00
2	FRONT BUMPER SIDE RETAINER L/R @\$125.30	NOT NECESSARY	\$250.60	\$0.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$431.10	\$0.00
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	\$27.90	\$0.00
1	FRONT BUMPER UNDER COVER (CENTER)	TORN	\$264.80	\$264.80
1	FRONT RH FENDER INNER SHIELD	TORN	\$483.60	\$359.00
1	FRONT WASHER TANK	DEFORMED	\$462.20	\$173.00
1	FRONT WASHER TANK MOTOR	NOT NECESSARY	\$310.60	\$0.00
1	REAR BUMPER	NOT NECESSARY	\$1,643.50	\$0.00
1	ROCKER GARNISH RH	DEFORMED	\$1,213.70	\$1,213.70
	LESS 10.00% DISCOUNT		(\$710.28)	(\$367.68)
			\$6,392.52	\$3,309.12

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	ENGINE OIL (SN)	NECESSARY	\$100.00	\$80.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET ROCKER GARNISH RH CLIPS (SN)	NECESSARY	\$50.00	\$30.00
			\$360.00	\$170.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	NOT NECESSARY	\$80.00	\$0.00
	TO REMOVE, INSTALL ENGINE WITH TRANSMISSION. (TO FR)	NOT NECESSARY	\$100.00	\$0.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,000.00	\$400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$800.00	\$400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$120.00	\$0.00
			\$2,100.00	\$800.00
GRAND TOTAL			\$8,852.52	\$4,279.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,400.00
Report Ref No: CS/INC24090164/Avh3e2				

TOTAL FOR SPARE PARTS: \$ 6,752.52 \$ 3,479.12
TOTAL FOR LABOUR : \$ 2,100.00 \$ 800.00
TOTAL REPAIR COST: \$ 8,852.52 \$ 4,279.12

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.