



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090167/Anh3e2
75 BRAS BASAH ROAD	Date:	22/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 4224C	Veh. Inspected	GBF 7971X
Policy No.	-	Coverage	0
Claim No.	MT/1294174-002	Excess	\$0.00
Assign From	AZHARI AFIDI	Assign Date	10/09/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA	C.C	2982
Engine No.	1KD2690738	Year of Reg.	16/03/2017
Chassis No.	JTFAT35Y50K207720	Colour	SILVER
Odometer	201332 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	TRIANGLE	6
L/H Front Tyre	195 R15C	TRIANGLE	6
R/H Rear Tyre	155 R12C	FALKEN	6
L/H Rear Tyre	155 R12C	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2024	Inspection Date	10/09/2024 (12:39)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days