

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG24090168/UNP3E2
Date: 26/09/2024REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 1002925293 |
| Claimant Vehicle No : | FBF5092X | Insured Vehicle No : | SNK7156P |
| Date of Loss: | 29/08/2024 | Nature of Claim: | TP |
| | | Claim No: | 372689 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-----------|
| Reg No: | FBF5092X | Engine No: | 4S3304610 |
| Make & Model: | YAMAHA X-1R, 134cc (M) | Chassis No: | 4S3304610 |
| Reg. Date: | 12/08/2011 (Man. Year: 2011) | Odometer: | 94480 km |
| Colour: | Black | | |
| Engine Capacity: | 135 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|--------------|
| Front Tyre Size: | 80-90-17 | Rear Tyre Size: | 90-80-17 |
| Front Left Side: | Maxxis 5 mm | Rear Left Side: | Pirelli 5 mm |
| Front Right Side: | 0 mm | Rear Right Side: | 0 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 10/09/2024 | | |
| Date Inspected: | 11/09/2024 | Inspected At: | Bisado Technologies LLP (HQ) 1 Kaki Bukit Ave 6, #02-32 Autobay @ Kaki Bukit Singapore 417883 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00
-\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Sep 2024)

Parts: N/A YAMAHA X-1R 134cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBF5092X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >