

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP RES / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client Record)
 Make of Vehicle: _____
 (Policy Condition)

Veh No: SMR5701D Yr Regn: 2020, Jan.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Fit C.C. 1317
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 92879 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GK33423661
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/55R16
 R: 185/55R16

Remark: They had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 10/09/24
 *Survey held at NSI
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front o/s.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP & PF</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: Yes (✓)</u>
	<u>PV: No ()</u>
	<u>Nett:</u>
	<u>6649.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Forward: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Addl Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Inve (\$ _____)

Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

JEFFREY SEOW CHUANG HAN
 BLK 26 TOA PAYOH EAST #07-172
 SINGAPORE 310026

Contact : 98002913

TAX INVOICE

Repair Code : CLM18259

Date in : 09/09/2024

Vehicle Num. : SMR5701D

Model : HONDA FIT 1.3GF CVT

Chassis/Eng# : GK33423661/L13B3938152

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>deltd</i>	1	551.70	551.70 <i>-</i>
FRONT BUMPER REINFORCEMENT <i>ren</i>	1	396.00	396.00 <i>+</i>
FRONT BUMPER RH FOG LAMP GARNISH <i>deltd</i>	1	39.40	39.40 <i>-</i>
FRONT BUMPER RH SIDE MOULDING <i>deltd</i>	1	21.00	21.00 <i>-</i>
FRONT BUMPER SIDE RETAINER L/R <i>ren</i>	2	14.50	29.00 <i>+</i>
FRONT RH HEADLAMP <i>deltd</i>	1	595.20	595.20 <i>-</i>
FRONT RH HEADLAMP LOWER BRACKET <i>deltd</i>	1	42.00	42.00 <i>-</i>
Subtotal before discount			1,674.30
Percentage discount 20%			334.86
Sub-total 1			1,339.44
FRONT BUMPER CLIPS - SET <i>m</i>	1	80.00	80.00 <i>30</i>
Subtotal before discount			80.00
Percentage discount 0%			0.00
Sub-total 2			80.00
Parts-total			1,419.44

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

80.00 *30*

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

400.00 *200*

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400.00 *200*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JEFFREY SEOW CHUANG HAN
BLK 26 TOA PAYOH EAST #07-172
SINGAPORE 310026

Contact : 98002913

TAX INVOICE

Repair Code : CLM18259
Date in : 09/09/2024
Vehicle Num. : SMR5701D
Model : HONDA FIT 1.3GF CVT
Chassis/Eng# : GK33423661/L13B3938152

To apply anti-rust chemical on repaired and replaced panel.	60.00
Labour Total	940.00
Parts & Labour Total	2,359.44

*** This is a computer-generated document which requires no signature.***

page 2

Adrian G
2/3 10/09/24.
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: