

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24090172/AVP3E2**Date:** 23/01/2025**REFERENCE**

Insured/Claimant:	SEAN LEE JUNN KIT	Policy No:	7240007167		
Date of Loss:	08/09/2024	Nature of Claim:	OD	Claim No:	1391885556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD539M		Engine No:	DFY615573
Make & Model:	AUDI Q3, 1.5 SB TFSI S TRONIC (LED REAR) (A)		Chassis No:	WAUZZZF31R1018403
Reg. Date:	23/01/2024 (Man. Year: 2023)		Odometer:	7001 km
Colour:	Green			
Engine Capacity:	1498 cc			
Market Value/New Car Price:	S\$210,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,180.00	2,318.96	3,861.04	62.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,772.00	2,922.00	1,850.00	38.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,952.00	5,240.96	5,711.04	52.15
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	10,552.00	4,840.96	5,711.04	54.12
+ GST 9.00/9.00% (S\$)	949.68	435.69	513.99	54.12
Nett Amount (S\$)	11,501.68	5,276.65	6,225.03	54.12

INSPECTION

Date of Assignment:	10/09/2024		
Date Inspected:	24/09/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,960.00 FS	*- FS
2	2		*REAR BUMPER DAMPER - LH / RH	Not Necessary	48.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	573.00 FS	*458.00 FS
4	1		*REAR BUMPER GRILLE - LH	Not Necessary	573.00 FS	*- FS
5	1		*REAR BUMPER PARKING AID SUPPORT - LH	Not Necessary	32.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR - LH	Cracked	49.00 FS	*38.72 FS
7	1		*REAR BUMPER ADAPTOR - H	Not Necessary	107.00 FS	*- FS
8	1		*REAR BUMPER BRACKET - LH	Not Necessary	60.00 FS	*- FS
9	1		*REAR PARKING AID SENSOR	Damaged	286.00 FS	*228.80 FS
10	4		*REAR PARKING AID SENSOR SEAL RING	Necessary	11.00 FS	*8.64 FS
11	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,278.00 FS	*1,022.40 FS
12	1		*SUNDRIES	Necessary	500.00 FS	*1.44 FS
13	1		*REAR BUMPER GRILLE TRIM LH (Supplementary)	Cracked	191.00 FS	*152.40 FS
14	1		*SUPPORT ULTRASOUND SENSOR LH (Supplementary)	Necessary	32.00 FS	*24.96 FS
15	1		*REAR BUMPER SENSOR WIRING SET (Supplementary)	Damaged	480.00 FS	*383.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,180.00	2,318.96
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND BOTH WHEEL ARCH TRIMS	New	1,800.00	1,050.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
5	TO REPAIR REAR END PANELLING (Supplementary)	New	250.00	250.00
6	TO RESPRAY REAR END PANELLING (Supplementary)	New	550.00	550.00
Gross Labour Cost (\$)			4,772.00	2,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >