

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24090173/UQP3E2

Date: 23/09/2024

REFERENCE

|                       |               |                      |              |           |                    |
|-----------------------|---------------|----------------------|--------------|-----------|--------------------|
| Handling Insurer:     | ECICS Limited | Policy No:           | DMPU2400044H |           |                    |
| Claimant Vehicle No : | SNM2607C      | Insured Vehicle No : | SLC6533G     |           |                    |
| Date of Loss:         | 05/09/2024    | Nature of Claim:     | TP           | Claim No: | DMPU2400044H/02/ST |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SNM2607C                     | Engine No:  | HIDDEN            |
| Make & Model:               | BYD E6 (ME-2), (A)           | Chassis No: | LC0CE4DC0N0486817 |
| Reg. Date:                  | 07/09/2023 (Man. Year: 2022) | Odometer:   | 101156 km         |
| Colour:                     | Blue                         |             |                   |
| Engine Capacity:            | 0 cc                         |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 215/55 R17 | Rear Tyre Size:  | 215/55 R17 |
| Front Left Side:  | Mozzo 6 mm | Rear Left Side:  | Mozzo 6 mm |
| Front Right Side: | Mozzo 6 mm | Rear Right Side: | Mozzo 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 15,154.76  | 1,776.60   | 13,378.16  | 88.28  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 3,300.00   | 1,230.00   | 2,070.00   | 62.73  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 18,454.76  | 3,006.60   | 15,448.16  | 83.71  |
| Approved Total (Overridden) (S\$) |            | 2,400.00   |            |        |
| (S\$)                             | 18,454.76  | 2,400.00   | 16,054.76  | 87.00  |
| + GST 9.00/9.00% (S\$)            | 1,660.93   | 216.00     | 1,444.93   | 87.00  |
| Nett Amount (S\$)                 | 20,115.69  | 2,616.00   | 17,499.69  | 87.00  |

INSPECTION

|                             |            |               |                                                                                         |
|-----------------------------|------------|---------------|-----------------------------------------------------------------------------------------|
| Date of Assignment:         | 10/09/2024 |               |                                                                                         |
| Date Inspected:             | 11/09/2024 | Inspected At: | Carsmith Private Limited (HQ)<br>8 Kaki Bukit Ave 4, #04-35 Premier<br>Singapore 415875 |
| Estimated Period of Repair: | 3.0 days   |               |                                                                                         |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



REPAIR DETAILS

|               |                                                                                                                                                                              |                                                     |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                     |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 23 Sep 2024)       |
| Parts:        | M1-MPV                                                                                                                                                                       | BYD E6 (ME-2) (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                   |
| Print Code:   | (Unsubmitted, no print-code for SNM2607C)                                                                                                                                    |                                                     |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                     |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                     |

Recommended Parts

| No.                                                 | Qty | Part No. | Particulars                           | Condition       | Repairer's  | Amount       |
|-----------------------------------------------------|-----|----------|---------------------------------------|-----------------|-------------|--------------|
| 1                                                   | 1   |          | *REAR BUMPER ASSY                     | Deformed / Torn | 2,985.00 FL | *1,270.00 FL |
| 2                                                   | 1   |          | *REAR BUMPER RETAINER LH              | Not Necessary   | 98.00 FL    | *- FL        |
| 3                                                   | 1   |          | *REAR BUMPER RETAINER RH              | Not Necessary   | 98.00 FL    | *- FL        |
| 4                                                   | 1   |          | *REAR BUMPER BRACKET LH               | Not Necessary   | 98.00 FL    | *- FL        |
| 5                                                   | 1   |          | *REAR BUMPER BRACKET RH               | Not Necessary   | 98.00 FL    | *- FL        |
| 6                                                   | 1   |          | *REAR BUMPER GRILLE BAR LH            | Not Necessary   | 105.00 FL   | *- FL        |
| 7                                                   | 1   |          | *REAR BUMPER GRILLE BAR RH            | Not Necessary   | 105.00 FL   | *- FL        |
| 8                                                   | 1   |          | *REAR BUMPER GRILLE BAR CENTER        | Cut             | 144.00 FL   | *144.00 FL   |
| 9                                                   | 1   |          | *REAR REFLECTOR LH                    | Not Necessary   | 198.00 FL   | *- FL        |
| 10                                                  | 1   |          | *REAR REFLECTOR RH                    | Not Necessary   | 198.00 FL   | *- FL        |
| 11                                                  | 1   |          | *REAR REFLECTOR CENTRE                | Cracked         | 425.00 FL   | *280.00 FL   |
| 12                                                  | 1   |          | *REAR END PANEL                       | Repair          | 852.00 FL   | *- FL        |
| 13                                                  | 1   |          | *REAR END PANEL TOP GARNISH           | Not Necessary   | 287.00 FL   | *- FL        |
| 14                                                  | 1   |          | *REAR REINFORCEMENT                   | Repair          | 565.00 FL   | *- FL        |
| 15                                                  | 2   |          | *REAR REINFORCEMENT BRACKET           | Not Necessary   | 352.00 FL   | *- FL        |
| 16                                                  | 1   |          | *TAILGATE                             | Repair          | 5,459.40 FL | *- FL        |
| 17                                                  | 1   |          | *TAILGATE LOGO                        | Not Necessary   | 108.00 FL   | *- FL        |
| 18                                                  | 1   |          | *TAILGATE EMBLEM BYD E6               | Necessary       | 108.00 FL   | *80.00 FL    |
| 19                                                  | 1   |          | *TAILGATE CHROME MOULDING             | Not Necessary   | 345.00 FL   | *- FL        |
| 20                                                  | 1   |          | *TAILGATE LOCK                        | Not Necessary   | 578.00 FL   | *- FL        |
| 21                                                  | 1   |          | *TAILGATE WEATHERSTRIP                | Not Necessary   | 373.00 FL   | *- FL        |
| 22                                                  | 2   |          | *TAILGATE HINGE                       | Not Necessary   | 176.00 FL   | *- FL        |
| 23                                                  | 1   |          | *TAILGATE SENSOR                      | Not Necessary   | 528.00 FL   | *- FL        |
| 24                                                  | 1   |          | *TAILGATE WINDSCREEN                  | Not Necessary   | 698.00 FL   | *- FL        |
| 25                                                  | 1   |          | *TAILGATE WIPER                       | Not Necessary   | 135.00 FL   | *- FL        |
| 26                                                  | 1   |          | *SET REAR BUMPER CLIP                 | Necessary       | 50.00 FS    | *30.00 FS    |
| 27                                                  | 1   |          | *REAR NUMBER PLATE W/GARNISH          | Not Necessary   | 90.00 FS    | *- FS        |
| 28                                                  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Not Necessary   | 50.00 FS    | *- FS        |
| 29                                                  | 1   |          | *REVERSE CAMERA                       | Not Necessary   | 480.00 FS   | *- FS        |
| 30                                                  | 1   |          | *REVERSE SENSOR                       | Serviceable     | 480.00 FS   | *- FS        |
| 31                                                  | 1   |          | *REVERSE SENSOR HOLDER                | Not Necessary   | 80.00 FS    | *- FS        |
| 32                                                  | 1   |          | *COMPANY STICKER                      | Necessary       | 200.00 FS   | *150.00 FS   |
| 33                                                  | 1   |          | *JOINT SEALANT                        | Not Necessary   | 120.00 FS   | *- FS        |
| F=Franchise part. S=SpcNett. L=ListItemDisc.        |     |          |                                       |                 |             |              |
| Sub Total (\$\$)                                    |     |          |                                       |                 | 16,666.40   | 1,954.00     |
| - List Item Discount on L Items 10.00/10.00% (\$\$) |     |          |                                       |                 | 1,511.64    | 177.40       |
| Total Parts (\$\$)                                  |     |          |                                       |                 | 15,154.76   | 1,776.60     |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                             | Particulars                                                           | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                       |          |                 |                 |
| 1                              | CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM               | New      | 150.00          | 20.00           |
| 2                              | REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR                 | New      | 200.00          | 0.00            |
| 3                              | REMOVE AND REFIX REAR REVERSE SENSOR                                  | New      | 150.00          | 30.00           |
| 4                              | REMOVE AND REFIT REAR ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH | New      | 200.00          | 0.00            |
| 5                              | PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS  | New      | 1,200.00        | 580.00          |
| 6                              | SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS                        | New      | 1,200.00        | 600.00          |
| 7                              | APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS                            | New      | 200.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                       |          | <b>3,300.00</b> | <b>1,230.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >