

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090176/AUA3Q2**Date:** 18/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240044584
Claimant Vehicle No : SGG4988D **Insured Vehicle No :** SJH3838U
Date of Loss: 06/09/2024 Nature of Claim: TP Claim No: 4630111471SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGG4988D**
Make & Model: MAZDA CX-30, 2.0 ELEGANCE (A) Engine No: PE31533516
Reg. Date: 30/07/2020 (Man. Year: 2020) Chassis No: JM6DM2W7AL0100543
Colour: Grey Odometer: 74330 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	793.84	30.00	763.84	96.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	400.00	750.00	65.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,943.84	430.00	1,513.84	77.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/09/2024
Date Inspected: 10/09/2024 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER LOWER AIR GRILLE	Not Necessary	527.10 FL	*- FL
2	1		*FRT BUMPER SIDE HOLDER RH	Not Necessary	173.40 FL	*- FL
3	1		*FRT NUMBER PLATE BASE	Not Necessary	215.80 FL	*- FL
4	8		*FRT BUMPER CLIPS	Necessary	60.80 FS	*30.00 FS
					Sub Total (\$\$)	977.10 30.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	183.26 0.00
					Total Parts (\$\$)	793.84 30.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	350.00	200.00
2	TO PUTTY AND RESPRAY PAINTING ON FRT BUMPER AND FRT BUMPER TOP	New	800.00	200.00
Gross Labour Cost (\$\$)			1,150.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >