

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090179/KMA3Q2
Date: 10/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230056055
Claimant Vehicle No :	SGW6111U	Insured Vehicle No :	SNL3513M
Date of Loss:	08/09/2024	Nature of Claim:	TP
		Claim No:	1252279071SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW6111U	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 RWD, (A)	Chassis No:	LRW3F7FS4RC022833
Reg. Date:	11/12/2023 (Man. Year: 2023)	Odometer:	10207 km
Colour:	Metallic Blue		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,920.24	2,824.29	2,095.95	42.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	730.00	2,020.00	73.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,670.24	3,554.29	4,115.95	53.66
+ GST 9.00/9.00% (S\$)	690.32	319.89	370.43	53.66
Nett Amount (S\$)	8,360.56	3,874.18	4,486.38	53.66
+ Car Rental (3.0 x S\$80.00/day + 9.00% GST) (S\$)		261.60		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		4,168.96		
Global Sum Settlement (S\$)		4,150.00		

INSPECTION

Date of Assignment:	10/09/2024	Optima Werkz Pte Ltd (HQ)
Date Inspected:	10/09/2024 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Estimated Period of Repair:	3.0 days	Autopoint
		Singapore 568047

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	695.04 FL	*695.04 FL
2	1		*FRONT RH BUMPER RETAINER	Distorted	7.09 FL	*7.09 FL
3	1		*FRONT RH BUMPER SIDE SUPPORT BRACKET	Cracked	11.28 FL	*11.28 FL
4	1		*FRONT BUMPER ENERGY ABSORBER	Serviceable	21.34 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	372.34 FL	*- FL
6	1		*FRONT RH BUMPER REINFORCEMENT BRACKET	Repair	49.64 FL	*- FL
7	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	49.64 FL	*49.64 FL
8	1		*FRONT RH BUMPER LOWER REINFORCEMENT BRACKET	Cracked	29.90 FL	*29.90 FL
9	1		*FRONT BUMPER LOWER GRILLE COVER	Dented	91.01 FL	*91.01 FL
10	1		*FRONT RADIATOR SUPPORT PANEL	Cracked	157.21 FL	*157.21 FL
11	1		*FRONT RH RADIATOR SUPPORT PANEL OUTER BRACKET	Serviceable	7.09 FL	*- FL
12	1		*FRONT BUMPER LOWER COVER	Distorted	182.03 FL	*182.03 FL
13	1		*FRONT RH HEADLAMP	Cracked	1,580.39 FL	*1,580.39 FL
14	1		*FRONT RH FENDER LINER	Cracked	106.73 FL	*106.73 FL
15	1		*FRONT RH KNUCKLE ARM	Serviceable	463.36 FL	*- FL
16	1		*FRONT RH KNUCKLE HUB+BEARING	Serviceable	233.64 FL	*- FL
17	1		*FRONT RH LOWER ARM -STRAIGHT	Serviceable	212.65 FL	*- FL
18	1		*FRONT RH LOWER ARM -CURVED	Serviceable	212.65 FL	*- FL
19	1		*FRONT RH UPPER ARM	Serviceable	105.91 FL	*- FL
20	1		*FRONT RH STEERING TIE ROD END	Serviceable	121.49 FL	*- FL
21	1		*FRONT PEDESTRIAN PROTECTION SENSOR	Serviceable	46.04 FL	*- FL
22	1		*RADIATOR	Serviceable	79.43 FL	*- FL
23	1		*RADIATOR FAN COWLING COMPLETE	Serviceable	84.11 FL	*- FL
24	1		*FRONT HOOD LOGO	Not Necessary	41.37 FL	*- FL
25	1		*FRONT HOOD (NPA)	Repair	0.00 FL	*- FL
26	1		*FRONT RH FENDER PANEL (NPA)	Repair	0.00 FL	*- FL
27	1		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
28	1		*FRONT BUMPER RIVETS	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT FENDER LINER CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*FRONT BUMPER UNDER COVER CLIPS	Necessary	50.00 FS	*50.00 FS
31	1		*RADIATOR COOLANT	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,416.38	3,115.32
- List Item Discount on L Items 10.00/10.00% (\$\$)	496.14	291.03
Total Parts (\$\$)	4,920.24	2,824.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	700.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER FRONT BONNET ,FRONT RH FENDER ETC	New	800.00	440.00
3	TO READJUST AND REALIGN HEADLAMP AIM	New	100.00	20.00
4	TO REMOVE AND REFIT RADIATOR AND OTHER NECESSARY ITEMS TO ENABLE REPAIR	New	200.00	0.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	0.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	250.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	20.00
8	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	150.00	0.00
9	TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	New	300.00	0.00
Gross Labour Cost (\$\$)			2,750.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >