

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090183/TVP3E2
Date: 15/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLH1480G	Insured Vehicle No :	SJL8668P
Date of Loss:	25/08/2024	Nature of Claim:	TP
		Claim No:	DMPC2401183H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH1480G	Engine No:	1ZR578674
Make & Model:	TOYOTA ALTIS, 1.6 (A)	Chassis No:	MR053REH104552203
Reg. Date:	26/10/2016 (Man. Year: 2016)	Odometer:	147627 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,668.86	2,092.80	4,576.06	68.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,370.00	1,050.00	43.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,088.86	3,462.80	5,626.06	61.90
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	9,088.86	2,750.00	6,338.86	69.74

INSPECTION

Date of Assignment:	11/09/2024	
Date Inspected:	11/09/2024	Inspected At: YS Auto Werkz (HQ) 10 Kaki Bukit Road 2 #01-03 First East Centre Singapore 417868
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2024)
Parts:	143	TOYOTA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH1480G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	820.80 FL	*- FL
2	1		*REAR BOOT INNER LOCK	Distorted	165.80 FL	*165.80 FL
3	1		*REAR BOOT WEATHERSTRIP	Cut	181.20 FL	*181.20 FL
4	1		*REAR BOOT COROLLA ALTIS EMBLEM	Necessary	68.90 FL	*68.90 FL
5	1		*REAR BOOT LAMP	N/S Not Necessary/O/S Cut	760.80 FL	*380.40 FL
6	1		*REAR TAIL LAMP	N/S Not Necessary/O/S Cracked	890.80 FL	*445.40 FL
7	1		*REAR END PANEL	Repair	780.90 FL	*- FL
8	1		*REAR END PANEL INNER GARNISH	Not Necessary	232.60 FL	*- FL
9	1		*REAR BUMPER	Deformed	685.50 FL	*482.00 FL
10	1		*REAR BUMPER BRACKETS	N/S Not Necessary/O/S Cracked	181.00 FL	*90.50 FL
11	1		*REAR BUMPER SIDE BRACKETS	N/S Not Necessary/O/S Deformed	191.80 FL	*95.90 FL
12	1		*REAR BUMPER REFLECTORS	N/S Not Necessary/O/S Cracked	196.60 FL	*98.30 FL
13	1		*REAR KEYLESS SENSOR	Not Necessary	477.30 FL	*- FL
14	1		*REAR BUMPER	Repeated	841.65 FL	*- FL
15	2		*REAR BUMPER BRACKETS	Not Necessary	146.00 FL	*- FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	179.60 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Repeated	102.80 FL	*- FL
18	1		*REAR REINFORCEMENT	Bent	786.90 FL	*462.00 FL
19	1		*REAR EXHAUST SILENCER	Not Necessary	654.20 FL	*- FL
20	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
21	1		*SET REAR REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,755.15	2,710.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,086.29	617.60
Total Parts (\$\$)	6,668.86	2,092.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACE DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	40.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIMS TO ASSIST REPAIR	New	80.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	40.00
4	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER	New	80.00	0.00
5	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	0.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	900.00	600.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,420.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >