



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 6681U

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER (N)	CUT/TORN	\$1,886.21	\$1,692.32
1	REAR BUMPER LOWER DIFFUSER (N)	SERVICEABLE	\$403.12	\$0.00
1	SET REAR BUMPER PDC SENSOR O/S (N)	SERVICEABLE	\$215.00	\$0.00
1	REAR BUMPER BEAM (N)	NOT NECESSARY	\$750.21	\$0.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	\$50.00	\$50.00
	LESS 10.00%		(\$330.45)	(\$174.23)
			\$2,974.09	\$1,568.09
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING }		\$50.00	\$40.00
	TO DISMANTLE & REFIX REAR PDC SENSOR }		\$80.00	\$0.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$380.00	\$200.00
	TO PUTTY & SPRAY PAINTING		\$420.00	\$200.00
			\$930.00	\$440.00
GRAND TOTAL			\$3,904.09	\$2,008.09
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,600.00
Report Ref No: CS/INC24090186/Unh3				

TOTAL FOR SPARE PARTS: \$ 2,974.09 \$ 1,568.09
TOTAL FOR LABOUR : \$ 930.00 \$ 440.00
TOTAL REPAIR COST: \$ 3,904.09 \$ 2,008.09

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.