

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090191/KUA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SKP6538L **Insured Vehicle No :** GBK3252M
 Date of Loss: 09/09/2024 Nature of Claim: TP Claim No: MFL2024D0010730

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6538L**
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520227963
 Reg. Date: 29/09/2014 (Man. Year: 2014) Chassis No: JM6BM42A8F0143542
 Colour: Metallic Red Odometer: 108590 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Toyo 9 mm Rear Left Side: Toyo 9 mm
 Front Right Side: Toyo 9 mm Rear Right Side: Toyo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,872.50	2,228.50	644.00	22.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,000.00	720.00	41.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,592.50	3,228.50	1,364.00	29.70
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	4,592.50	2,550.00	2,042.50	44.47
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/09/2024
 Date Inspected: 12/09/2024 Inspected At: Optima Werkz Pte Ltd (HQ)
 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2024)
Parts: 143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP6538L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	550.00 FL	*550.00 FL
2	1		*FRONT RH BUMPER RETAINER	Distorted	15.00 FL	*15.00 FL
3	1		*FRONT RH BUMPER FOG LAMP OUTER BLACK GARNISH	Cut	50.00 FL	*50.00 FL
4	1		*FRONT RH BUMPER FOG LAMP CHROME COVER	Dented	80.00 FL	*80.00 FL
5	1		*FRONT RH HEADLAMP WASHER COVER	Dented	60.00 FL	*60.00 FL
6	1		*FRONT RH HEADLAMP WASHER NOZZLE JET	*Check	160.00 FL	*- FL
7	1		*FRONT RH HEADLAMP	Cut	1,480.00 FL	*1,480.00 FL
8	1		*FRONT RH FENDER PANEL	Buckled	180.00 FL	*180.00 FL
9	1		*FRONT BUMPER RADIATOR GRILLE UPPER COVER (NPA)	Repair	0.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
11	1		*FRONT BUMPER RIVETS	Not Necessary	50.00 FS	*- FS
12	1		*FRONT FENDER LINER CLIPS	Not Necessary	50.00 FS	*- FS
13	1		*FRONT BUMPER SPOILER	Repair	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,130.00	2,470.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	257.50	241.50
Total Parts (\$\$)	2,872.50	2,228.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REFIX ,REPAIR & READJUST FRONT RH ACCIDENT AREAS & ETC	New	700.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT RH FENDER ,ETC	New	700.00	550.00
3	TO READJUST AND ALIGN HEADLAMP AIM	New	100.00	20.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			1,720.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >