



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMN 5617K

| REPLACEMENT OF PARTS                 |  |               |                        |                   |
|--------------------------------------|--|---------------|------------------------|-------------------|
| Qty                                  | Description of Parts   | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                                    | REAR BUMPER  | DEFORMED      | \$967.00               | \$475.00          |
| 1                                    | REAR BUMPER SIDE HOLDER RH   | NOT NECESSARY | \$54.00                | \$0.00            |
|                                      | LESS 20.00% DISCOUNT   |               | (\$204.20)             | (\$95.00)         |
|                                      |  |               | \$816.80               | \$380.00          |
| Special Nett                         |  |               |                        |                   |
| Qty                                  | Description of Parts   | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
| 8                                    | REAR BUMPER CLIPS @\$6.80 (SN)   | NECESSARY     | \$54.40                | \$30.00           |
|                                      |  |               | \$54.40                | \$30.00           |
| Labour                               |  |               |                        |                   |
|                                      | Description of Parts   | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
|                                      | TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT |               | \$700.00               | \$200.00          |
|                                      | TO PUTTY AND RESPRAY PAINTING ON REAR BUMPER AND REAR FENDER RH  |               | \$800.00               | \$400.00          |
|                                      |  |               | \$1,500.00             | \$600.00          |
| GRAND TOTAL                          |  |               | \$2,371.20             | \$1,010.00        |
|                                      | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)                       |               |                        | \$800.00          |
| Report Ref No: CS/INC24090192/Aqh3e2 |  |               |                        |                   |

TOTAL FOR SPARE PARTS: \$ 871.20 \$ 410.00  
TOTAL FOR LABOUR : \$ 1,500.00 \$ 600.00  
TOTAL REPAIR COST: \$ 2,371.20 \$ 1,010.00

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.