

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401923

INV Date : 19-12-2024

Reference CD/LPC24090195/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 4342K
Insured Veh. XE 7389Y
Claim No. 24/24/24/VC05/029776
Policy No. Z24VC05025081
Accident Date 28/08/2024
Inspection Date 11/09/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24090195/Rpa3q2
300 BEACH ROAD	Date:	19/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	XE 7389Y	Veh. Inspected	GBJ 4342K
Policy No.	Z24VC05025081	Coverage	0
Claim No.	24/24/24/VC05/029776	Excess	\$0.00
Assign From	CHARMAINE KONG	Assign Date	11/09/2024

2. Vehicle Details

Make & Model	YD25045290B NV350 PANEL VAN 2.5 5MT 5DR	C.C	2488
Engine No.	YD25045290B	Year of Reg.	25/04/2019
Chassis No.	JN1MC2E26Z0030966	Colour	GREY
Odometer	256031 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	AUSTONE	7
L/H Front Tyre	195 R15C	AUSTONE	7
R/H Rear Tyre	195 R15C	AUSTONE	7
L/H Rear Tyre	195 R15C	AUSTONE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2024	Inspection Date	11/09/2024
Survey held at	VENDA ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT WESTVILLE SINGAPORE 648541		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBJ 4342K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN	NOT NECESSARY	\$1,100.40	\$0.00
1	FRONT WIPER PANEL	NOT NECESSARY	\$406.40	\$0.00
1	FRONT PANEL	BUCKLED	\$1,227.50	\$1,227.50
1	FRONT RADIATOR GRILLE	CRACKED	\$596.20	\$596.20
5	FRONT RADIATOR GRILLE CLIP @\$10.00	NECESSARY	\$50.00	\$50.00
1	FRONT BUMPER	CUT	\$611.90	\$611.90
1	FRONT BUMPER GRILLE	NOT NECESSARY	\$155.20	\$0.00
2	FRONT BUMPER SIDE RETAINER RH & LH @\$198.50	NOT NECESSARY	\$397.00	\$0.00
1	FRONT EMBLEM	NECESSARY	\$109.90	\$109.90
1	WIPER TANK	NOT NECESSARY	\$284.20	\$0.00
1	WIPER HOSE	NOT NECESSARY	\$140.00	\$0.00
1	HEATER ASSY	NOT NECESSARY	\$2,716.00	\$0.00
1	HEATER AIR DUCT	NOT NECESSARY	\$164.20	\$0.00
1	AIRCON BLOWER ASSY	NOT NECESSARY	\$1,047.10	\$0.00
2	FRONT HEADLAMP RH & LH @\$664.30	O/S CRACKED / N/S NOT NECESSARY	\$1,328.60	\$664.30
2	FRONT FOG LAMP COVER RH & LH @\$311.80	NOT NECESSARY	\$623.60	\$0.00
	LESS 10.00% DISCOUNT		(\$1,095.82)	(\$325.98)
			\$9,862.38	\$2,933.82

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	\$50.00	\$0.00
2	SILICONE @\$50.00 (SN)	NOT NECESSARY	\$100.00	\$0.00
2	PRIMER @\$30.00 (SN)	NOT NECESSARY	\$60.00	\$0.00
			\$210.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE & RENEW PARTS ,PANEL BEAT & REALIGN FRONT PORTION CUT & WELD FRONT PANEL		\$1,000.00	\$700.00
	DISMANTLE & REINSTALL FRONT WINDSCREEN	NOT NECESSARY	\$150.00	\$0.00
	DISMANTLE & REINSTALL FRONT DASHBOARD	NOT NECESSARY	\$300.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TOP UP GAS	NOT NECESSARY	\$100.00	\$0.00
	PUTTY & SPRAY PAINT FRONT PANEL FRONT BUMPER FRONT RH & LH CORNER PANEL		\$850.00	\$400.00
			\$2,400.00	\$1,100.00
GRAND TOTAL			\$12,472.38	\$4,033.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,200.00
Report Ref No: CD/LPC24090195/Rpa3q2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K




PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K



PHOTOGRAPHS FOR VEHICLE NO. : GBJ 4342K

