

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24090200/RVP3E2**Date:** 03/10/2024REFERENCEInsured/Claimant: CYCLE & CARRIAGE LEASING PTE LTD
Date of Loss: 03/09/2024Policy No: MCF24B00000800
Nature of Claim: OD

Claim No: DMCF2400059H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBM4389K	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ EVITO, 112 LONG (A)	Chassis No:	W1V44760324208454
Reg. Date:	15/09/2023 (Man. Year: 2022)	Odometer:	30899 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55Z R17	Rear Tyre Size:	225/55Z R17
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	60.00	60.00	0.00	0.00
Labour	1,120.00	900.00	220.00	19.64
Paintwork Labour	600.00	600.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,780.00	1,560.00	220.00	12.36
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
- Top-Up Amount (S\$)	0.00	3,000.00	-3,000.00	
(S\$)	780.00	-2,440.00	3,220.00	412.82
+ GST 9.00/9.00% (S\$)	70.20	-219.60	289.80	412.82
Nett Amount (S\$)	850.20	-2,659.60	3,509.80	412.82

INSPECTION

Date of Assignment:	11/09/2024	Present Location:	Diplomat Parts Pte Ltd (HQ)
Date Inspected:	12/09/2024	Inspected At:	Diplomat Parts Pte Ltd (HQ) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Oct 2024)	
Parts:	N/A	MERCEDES-BENZ EVITO 112 LONG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM4389K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRIM, BUMPER (NPA)	Deformed	-	*- F
2	1		*REINFORCEMENT, BUMPER (NPA)	Cracked	-	*- F
3	1		*COVER (NPA)	Not Necessary	-	*- F
4	1		*MOUNTING RAIL (NPA)	Cracked	-	*- F
5	1		*BRACING (NPA)	Not Necessary	-	*- F
6	1		*ELECTRICAL WIRING HARNESS (NPA)	Not Necessary	-	*- F
7	1		*CENTRAL LOCKING MOTOR (NPA)	Not Necessary	-	*- F
8	1		*BUTTON SWITCH (NPA)	Not Necessary	-	*- F
9	1		*COUPLING, MECHANICAL (NPA)	Not Necessary	-	*- F
10	1		*CLUTCH HOUSING (NPA)	Not Necessary	-	*- F
11	1		*ELECTRICAL WIRING HARNESS (NPA)	Not Necessary	-	*- F
12	1		*LAMP UNIT (NPA)	Broken	-	*- F
13	1		*FENDER, FRONT (NPA)	Buckled	-	*- F
14	1		*HEXALOBULAR BOLT (NPA)	Necessary	-	*- F
15	1		*HOLDER (NPA)	Not Necessary	-	*- F
16	1		*INTERMEDIATE LAYER (NPA)	Necessary	-	*- F
17	1		*BADGE (NPA)	Necessary	-	*- F
18	1		*TRIM, WHEEL HOUSING (NPA)	Cracked	-	*- F
19	1		*EXPANSION RIVET (NPA)	Necessary	-	*- F
20	1		*PLASTIC NUT (NPA)	Necessary	-	*- F
21	1		*CROSSMEMBER (NPA)	Not Necessary	-	*- F
22	1		*CARRIER (NPA)	Cracked	-	*- F
23	1		*HOLDER (NPA)	Not Necessary	-	*- F
24	1		*HOLDER (NPA)	Not Necessary	-	*- F
25	1		*BUMPER HOLDER (NPA)	Bent	-	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*LINK BLOCK (NPA)	Cracked	-	*- F
27	1		*LINK BLOCK (NPA)	Not Necessary	-	*- F
28	1		*SOCKET COVER (NPA)	Not Necessary	-	*- F
29	1		*CENTRAL LOCKING MOTOR (NPA)	Not Necessary	-	*- F
30	1		*SENSOR (NPA)	Cracked	-	*- F
31	1		*CHARGING FLAP (NPA)	Cracked	-	*- F
32	1		*WHEEL CAP (NPA)	Scratched	-	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ANTI-RUST PROOFING	30.00	30.00
2	1	APPLY BODY SEALANT ON AFFECTED AREA	30.00	30.00
Sub Total (\$\$)			60.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	BONNET	New	200.00	200.00
2	FRT LHS FENDER	New	200.00	200.00
3	FRT LHS DOOR	New	200.00	200.00
Labour Items				
4	FRT BUMPER	New	330.00	220.00
5	FRT LHS FENDER	New	330.00	220.00
6	To Conduct Computerize Full Wheel Alignment	New	60.00	60.00
7	TO CHECK WIRING CHASSIS ELECTRICAL AND EV SYSTEM	New	150.00	150.00
8	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	250.00	250.00
Gross Labour Cost (\$\$)			1,720.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >