

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090201/AVP3M4**Date:** 12/09/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002842702
Claimant Vehicle No :	SMU3519L	Insured Vehicle No :	FBT2364H
Date of Loss:	05/07/2024	Nature of Claim:	TP
		Claim No:	366799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU3519L		
Make & Model:	MERCEDES-BENZ GLA200, 1.6 URBAN (R18 LED) (A)	Engine No:	27091031788746
Reg. Date:	30/11/2018 (Man. Year: 2018)	Chassis No:	WDC1569432J573717
Colour:	White	Odometer:	80946 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,857.10	760.50	12,096.60	94.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	450.00	2,400.00	84.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,707.10	1,210.50	14,496.60	92.29

INSPECTION

Date of Assignment:	11/09/2024	
Date Inspected:	17/09/2024	Inspected At:
Estimated Period of Repair:	3.0 days	

TSL AUTO PRO SELECTION PTE LTD
BLK 1 KAKI BUKIT AVENUE 6
#01-06 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2025)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.6 URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU3519L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,685.00 FL	*- FL
2	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	72.00 FL	*- FL
3	1		*FRONT BUMPER SENSOR	Not Necessary	292.00 FL	*- FL
4	1		*HEADLAMP	Not Necessary	3,801.00 FL	*- FL
5	1		*FRONT FENDER	Repair	1,012.00 FL	*- FL
6	1		*FRONT FENDER ARC GARNISH	Not Necessary	266.00 FL	*- FL
7	1		*FRONT DOOR	Repair	2,342.00 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	317.00 FL	*- FL
9	1		*FRONT DOOR WING MIRROR	Not Necessary	1,154.00 FL	*- FL
10	1		*FRONT DOOR WING MIRROR GLASS	Not Necessary	265.00 FL	*- FL
11	1		*FRONT DOOR WING MIRROR SIGNAL LAMP	Not Necessary	291.00 FL	*- FL
12	1		*FRONT DOOR WING MIRROR COVER	Repair	182.00 FL	*- FL
13	1		*FRONT WHEEL RIM	Not Necessary	1,295.00 FL	*- FL
14	1		*ROCKER PANEL SIDE SKIRTING	Cut	845.00 FL	*845.00 FL
15	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*SET FRONT FENDER ARC GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
17	1		*FRONT TYRE	Not Necessary	300.00 FS	*- FS
18	1		*SET ROCKER PANEL SIDE SKIRTING CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,239.00	845.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,381.90	84.50
Total Parts (\$\$)	12,857.10	760.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,000.00	200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	250.00
3	WIRING CHECK	New	100.00	0.00
4	TO APPLY TUFF COAT	New	150.00	0.00
5	TO REMOVE FRONT BUMPER SENSOR	New	100.00	0.00
6	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
7	TO PERFORM DIAGNOSTIC TEST	New	200.00	0.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$\$)			2,850.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >