

REF:

CS/MSG 24090001 / Avp3

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____ m/s _____ 9150 9413

of _____

Insured: **FBT 2364H**Policy No **1002842702**Claims No **366799**

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMU3519L** Yr Regn: **2018, NOV**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mercedes Benz G400** **1595**Colour: **White** A/C: Insured / Std / NI / NASp. Reading: **80946** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WDC1569432J573717**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: **235/50R18**R: **235/50R18**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **06** mmL/Bal. **06** mmD.O.A. **5/7/24**

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. **06** mmL/Bal. **06** mmD.O.I. **17/09/24**

TSL

Date / Time

Action / Instruction

TP MS/G

10/9/25 Final fig \$1210.50 (red 14,496.60, 92%)

COE Expiry

Estimate given during: Yes ()

1st Survey: No (✓)

MV:

PV:

Nett:

615J.

Date/Time, File Pass to?

☐: Preli. ReportDays Of Repair: **5**

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

☐: Final Report

2)

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Form / P.P.P.P.

TSL AUTO GARAGE

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT
SINGAPORE 417883

TO	: MSIG	DATE	17/9/2024
VEHICLE NO	: SMU3519L (2018)		Veron
VEHICLE MODEL	: MERCEDES BENZ GLA200		
CHASSIS NO	: WDC1569432J573717		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER	1	\$ 1,685.00	\$ 1,685.00
2	FRONT BUMPER SIDE HOLDER	1	\$ 72.00	\$ 72.00
3	FRONT BUMPER SENSOR	1	\$ 292.00	\$ 292.00
4	HEADLAMP <i>ut</i> nn	1	\$ 3,801.00	\$ 3,801.00
5	FRONT FENDER <i>nn</i>	1	\$ 1,012.00	\$ 1,012.00
6	FRONT FENDER ARC GARNISH <i>ut</i> nn	1	\$ 266.00	\$ 266.00
7	FRONT DOOR <i>nn</i>	1	\$ 2,342.00	\$ 2,342.00
8	FRONT DOOR WEATHERSTRIPE <i>nn</i>	1	\$ 317.00	\$ 317.00
9	FRONT DOOR WING MIRROR <i>nn</i>	1	\$ 1,154.00	\$ 1,154.00
10	FRONT DOOR WING MIRROR GLASS <i>nn</i>	1	\$ 265.00	\$ 265.00
11	FRONT DOOR WING MIRROR SIGNAL LAMP <i>ut</i> nn	1	\$ 291.00	\$ 291.00
12	FRONT DOOR WING MIRROR COVER <i>nn</i>	1	\$ 182.00	\$ 182.00
13	FRONT WHEEL RIM <i>ut</i> nn	1	\$ 1,295.00	\$ 1,295.00
14	ROCKER PANEL SIDE SKIRTING <i>ut</i>	1	\$ 845.00	\$ 845.00

TOTAL PRICE: \$ 13,719.00
LESS 10% \$ 1,371.90
SUB TOTAL PRICE: \$ 12,347.10

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>nn</i>	1 SET	\$ 50.00	\$ 50.00
2	FRONT FENDER ARC GARNISH CLIPS <i>nn</i>	1 SET	\$ 20.00	\$ 20.00
3	FRONT TYRE <i>nn</i>	1	\$ 300.00	\$ 300.00
4	ROCKER PANEL SIDE SKIRTING CLIPS <i>nn</i>	1 SET	\$ 50.00	\$ 50.00

TOTAL: \$ 420.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	850	200
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	250
3	WIRING CHECK	\$ 160.00	30	X
4	TO APPLY TUFF COAT	\$ 150.00	30	X
5	TO REMOVE FRONT BUMPER SENSOR	\$ 100.00	X	
6	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	X	
7	TO PERFORM DIAGNOSTIC TEST	\$ 200.00	X	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	X

TOTAL: \$ 2,850.00

ESTIMATE REPORT

TOTAL PARTS COST:	\$	12,767.10
TOTAL LABOUR COST:	\$	2,850.00
TOTAL REPAIR COST:	\$	15,617.10

total 17008.20

L/S: 5.61c

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5.61c