



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400644

INV Date : 18-09-2024

Reference CS3/SMR24090207/Knp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. FBQ 5424P
Insured Veh. SHB 983H
Claim No. TAX/09/24/2004
Policy No.
Accident Date 03/09/2024
Inspection Date 11/09/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Ref: Date: Code:	CS3/SMR24090207/Knp3m4 18/09/2024 SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY			
Insured Veh.	SHB 983H	Veh. Inspected	FBQ 5424P
Policy No.	-	Coverage	0
Claim No.	TAX/09/24/2004	Excess	\$0.00
Assign From	ANA	Assign Date	10/09/2024
2. Vehicle Details			
Make & Model	YAMAHA AEROX	C.C	155
Engine No.	G3J1E0434450	Year of Reg.	29/10/2019
Chassis No.	MH3SG4620KJ069295	Colour	BLACK
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	100/80R14	MAXXIS	4
L/H Front Tyre			
R/H Rear Tyre	140/70R14	SHINKO	3
L/H Rear Tyre			
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.			
5. General Information			
Accident Date	03/09/2024	Inspection Date	11/09/2024 (11:03)
Survey held at	SOON HIN MOTORS PTE LTD - BLK 1018 #01-342 YISHUN INDUSTRIAL PARK A, SINGAPORE 768760		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBQ 5424P



PHOTOGRAPHS FOR VEHICLE NO. : FBQ 5424P



PHOTOGRAPHS FOR VEHICLE NO. : FBQ 5424P



PHOTOGRAPHS FOR VEHICLE NO. : FBQ 5424P

