

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24060157/UQH3E2
Date: 15/07/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001435891		
Claimant Vehicle No :	SJV4356M	Insured Vehicle No :	SKC5085B		
Date of Loss:	17/06/2024	Nature of Claim:	TP	Claim No:	363500

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV4356M		
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FCAH900624
Reg. Date:	26/01/2010 (Man. Year: 2009)	Chassis No:	KNAFW411MA5176942
Colour:	White	Odometer:	447570 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R18	Rear Tyre Size:	205/55 R18
Front Left Side:	Arivo 6 mm	Rear Left Side:	Premio 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Premio 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,295.20	1,621.50	5,673.70	77.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	890.00	3,610.00	80.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	11,795.20	2,511.50	9,283.70	78.71
Approved Total (Overridden) (\$)		2,000.00		
Nett Amount (\$)	11,795.20	2,000.00	9,795.20	83.04

INSPECTION

[illegible]

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2024)
Parts:	143	KIA CERATO FORTE 1.6 SX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV4356M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	1,022.00 FL	*- FL
2	1		*REAR BOOTLID HINGE LH	Not Necessary	65.00 FL	*- FL
3	1		*REAR BOOTLID HINGE RH	Not Necessary	65.00 FL	*- FL
4	1		*REAR BOOTLID INSULATOR	Not Necessary	213.00 FL	*- FL
5	1		*REAR BOOTLID LOCK	Not Necessary	390.00 FL	*- FL
6	1		*REAR BOOTLID INNER LAMP LH	Not Necessary	409.00 FL	*- FL
7	1		*REAR BOOTLID INNER LAMP RH	Not Necessary	409.00 FL	*- FL
8	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	219.00 FL	*- FL
9	1		*REAR BOOTLID NUMBER PLATE LAMP LH	Not Necessary	54.00 FL	*- FL
10	1		*REAR BOOTLID NUMBER PLATE LAMP RH	Not Necessary	54.00 FL	*- FL
11	2		*REAR BOOTLID STOPPER	Not Necessary	48.00 FL	*- FL
12	1		*REAR BUMPER	Torn	795.00 FL	*755.00 FL
13	1		*REAR BUMPER RETAINER LH	Not Necessary	65.00 FL	*- FL
14	1		*REAR BUMPER RETAINER RH	Not Necessary	65.00 FL	*- FL
15	1		*REAR BUMPER SPONGE	Torn	155.00 FL	*155.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	384.00 FL	*384.00 FL
17	1		*REAR BUMPER LOWER GARNISH	Grazed	509.00 FL	*241.00 FL
18	1		*REAR TAILLAMP LH	Not Necessary	498.00 FL	*- FL
19	1		*REAR TAILLAMP RH	Not Necessary	498.00 FL	*- FL
20	1		*REAR TAILLAMP PANEL LH	Not Necessary	299.00 FL	*- FL
21	1		*REAR TAILLAMP PANEL RH	Not Necessary	299.00 FL	*- FL
22	1		*END PANEL	Repair	694.00 FL	*- FL
23	1		*END PANEL TOP GARNISH	Not Necessary	219.00 FL	*- FL
24	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
26	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
27	1		*BOOTLID INSULATOR CLIP	Not Necessary	30.00 FS	*- FS
28	1		*SET REAR REVERSE SENSOR	Malfunction	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,038.00	1,775.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	742.80	153.50
Total Parts (\$\$)	7,295.20	1,621.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	150.00	20.00
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	New	150.00	0.00
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	New	200.00	40.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
5	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
6	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
7	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	0.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	New	250.00	0.00
9	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,500.00	400.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	400.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$)			4,500.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >