9/3/25, 11:52 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090210/AMA3Q2

03/09/2025 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04

Claimant Vehicle SBL9863E Insured Vehicle No: GBK3139H

No:

Date of Loss: 30/08/2024 Nature of Claim: TP Claim No: MFL2024D0010189

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBL9863E**

Make & Model: MERCEDES-BENZ 190E, 2.0 (A) Engine No: 10292422015055 Reg. Date: 01/03/1990 (Man. Year: 1989) Chassis No: WDB2010232F667922

Colour: Gold Odometer: 528392 km

Engine Capacity: 1977 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/45 R16 Rear Tyre Size: 205/45 R16 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,423.70	1,380.60	1,043.10	43.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	530.00	620.00	53.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,573.70	1,910.60	1,663.10	46.54
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	3,573.70	1,500.00	2,073.70	58.03
+ GST 9.00/9.00% (S\$)	321.63	135.00	186.63	58.03
Nett Amount (S\$)	3,895.33	1,635.00	2,260.33	58.03
+ Loss of Use (3.0 x S\$	100.00/day) (S\$)	300.00		
+ Doc	Search Fee (S\$)	2.18		
N	lett Liability (S\$)	1,937.18		

INSPECTION

Date of Assignment: 10/06/2025

Date Inspected: 10/06/2025 Inspected At:

Blk 3023A Ubi Road 1, #01-61 & #01-58

Modern Automotive Pte Ltd (HQ)

Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager: Daphne Lee Mooi Ngiuk NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Aug 2025)

Parts: 143 MERCEDES-BENZ 190E 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBL9863E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,298.00 FL	*1,298.00 FL
2	1		*FRONT BUMPER PAD	Not Necessary	401.00 FL	*- FL
3	1		*FRONT SIGNAL LAMP	Cracked	236.00 FL	*236.00 FL
4	1		*FRONT DOOR WING MIRROR	Not Necessary	758.00 FL	*- FL
F=Fra	anchise	part. L=ListIten	nDisc.	_		
				Sub Total (S\$)	2,693.00	1,534.00
			- List Item Discount	on L Items 10.00/10.00% (S\$)	269.30	153.40
				Total Parts (S\$)	2,423.70	1,380.60
			Report was unsubmi	tted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO KNOCKING & PULL OUT RH SIDE PORTION & RENEW ABOVE PARTS	New	500.00	250.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	600.00	250.00
3	TO CHECK WIRING	New	50.00	30.00
	Gross Lab	our Cost (S\$)	1,150.00	530.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >