



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090212/Rnp3e2
16 RAFFLES QUAY	Date:	12/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2037G	Veh. Inspected	SMH 3523S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007975MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	12/09/2024

2. Vehicle Details

Make & Model	SUZUKI VITARA 1.6 GLX	C.C	1586
Engine No.	M16A2217651	Year of Reg.	21/01/2019
Chassis No.	TSMLYD21S00441878	Colour	ORANGE
Odometer	101957 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55 R17	PIRELLI	6
L/H Front Tyre	215/55 R17	PIRELLI	6
R/H Rear Tyre	215/55 R17	PIRELLI	6
L/H Rear Tyre	215/55 R17	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2024	Inspection Date	30/09/2024
Survey held at	48 TOH GUAN ROAD EAST #02-146/147 S608586 - REPAIRER: AUTOMOTIVE REPAIR CENTRE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days