

ASS. REC. BY:

REF:

A/G 124090213/kmas

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Cavan Motor  
of 38114

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: £75K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: 09/30 Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SN6 321X Yr Regn: 06, 10Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Traller or A)Make: BMW 523i C.C. 2497Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 118621 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAFP 320500546261Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NI / S/Rlm / STD A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: 245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 9/9/24D.O.I. 11/9/2024Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/9 21 Pm @ 48501 Cavan

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \_\_\_\_\_

Fees: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

源摩哆廠

# GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

## REPAIR ESTIMATE FOR SNG321X

| No. | Qty | List Items                                                                   |                                      |             |             |
|-----|-----|------------------------------------------------------------------------------|--------------------------------------|-------------|-------------|
| 1   | 1   | Front bumper                                                                 | <i>Buyer</i>                         | 1,485.50    | ✓           |
| 2   | 1   | Front bumper RH parking sensor                                               | \$ <i>Car</i>                        | 256.80      | ✓           |
| 3   | 1   | Front bumper RH fog lamp cover                                               | \$ <i>Sm</i>                         | 89.00       | X           |
| 4   | 1   | Front bumper RH fog lamp                                                     | \$ <i>Car</i>                        | 315.15      | ✓           |
| 5   | 1   | Front bumper RH headlamp washer nozzle                                       | \$ <i>Sm</i>                         | 201.50      | X           |
| 6   | 1   | Front bumper RH side retainer                                                | \$ <i>Sm</i>                         | 33.80       | X           |
| 7   | 1   | Rear bumper inner foam                                                       | \$ <i>Sm</i>                         | 118.00      | X           |
| 8   | 1   | Rear bumper inner reinforcement                                              | \$ <i>As</i>                         | 843.95      | ✓           |
| 9   | 1   | Rear bumper inner parts                                                      | \$ <i>Sm</i>                         | 210.95      | X           |
| 10  | 1   | RH headlamp                                                                  | \$ <i>Car</i>                        | 2,896.40    | ✓           |
|     |     |                                                                              | \$                                   | 6,451.05    |             |
|     |     |                                                                              | Less 5%                              | \$ 322.55   |             |
|     |     |                                                                              | Total :                              | \$ 6,128.50 |             |
|     |     |                                                                              |                                      |             |             |
|     |     |                                                                              | <u>Labour</u>                        |             |             |
| 1   |     | Labour Charges for remove/refit, cutting/welding and replacement of damages. | \$                                   | 500.00      | <i>250l</i> |
| 2   |     | To putty and spray Spray Paintings charges.                                  | \$                                   | 500.00      | <i>250l</i> |
| 3   |     | To check wirings and lightings.                                              | \$                                   | 40.00       | <i>20l</i>  |
| 4   |     | To remove, refit & reset front bumper parking sensors.                       | \$                                   | 80.00       | <i>60l</i>  |
| 5   |     | To supply and apply anti rust treatment                                      | \$ <i>nn</i>                         | 30.00       | X           |
|     |     |                                                                              | Total :                              | \$ 1,150.00 |             |
|     |     |                                                                              | Total Parts and Labour : \$ 7,278.50 |             |             |

*Not Notified*

*11 Pm @ 4850h*

*Recovery After Repair*

*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: