

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24090214/KPA3Q2  
**Date:** 09/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900112027-04
<b>Claimant Vehicle No :</b>	SMR1270G	<b>Insured Vehicle No :</b>	SMM3612S
Date of Loss:	03/09/2024	Nature of Claim:	TP
			Claim No: 1795298618SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMR1270G</b>	Engine No:	L15B6020435
Make & Model:	HONDA SHUTTLE, 1.5 G CVT SENSING (A)	Chassis No:	GK82100356
Reg. Date:	20/12/2019 (Man. Year: 2019)	Odometer:	298564 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,264.32	2,604.32	2,660.00	50.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,270.00	1,050.00	45.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,584.32</b>	<b>3,874.32</b>	<b>3,710.00</b>	<b>48.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
	<b>(S\$)</b>	7,584.32	3,100.00	4,484.32
<b>+ GST 9.00/9.00% (S\$)</b>	682.59	279.00	403.59	59.13
<b>Nett Amount (S\$)</b>	<b>8,266.91</b>	<b>3,379.00</b>	<b>4,887.91</b>	<b>59.13</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 9.00% GST) (S\$)</b>		327.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>3,733.25</b>		

**INSPECTION**

Date of Assignment:	10/09/2024	
Date Inspected:	10/09/2024	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.70 FL	*1,193.70 FL
2	1		*REAR TAILGATE H LOGO	Necessary	58.00 FL	*58.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
4	1		*REAR TAILGATE OUTER GARNISH	Serviceable	480.50 FL	*- FL
5	1		*REAR TAILGATE RH REFLECTOR	Serviceable	380.20 FL	*- FL
6	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*121.60 FL
7	1		*REAR TAILGATE INNER RUBBER	Dented / Distorted	188.50 FL	*188.50 FL
8	1		*REAR TAILGATE INNER LOCK	Repair	385.20 FL	*- FL
9	1		*REAR RH TAILLAMP	Serviceable	581.50 FL	*- FL
10	1		*REAR BUMPER	Mtg Cracked	1,150.60 FL	*936.00 FL
11	1		*REAR BUMPER CENTRE CHROME	Necessary	195.50 FL	*166.00 FL
12	1		*REAR BUMPER RH SIDE REFLECTOR	Serviceable	125.50 FL	*- FL
13	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	58.20 FL	*- FL
14	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
15	1		*REAR END PANEL	Repair	685.00 FL	*- FL
16	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	285.50 FL	*186.60 FL
17	1		*SET REAR PARKING SENSOR	Dented / Shorted	280.00 FS	*200.00 FS
18	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
19	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,477.90</b>	<b>3,195.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,213.58	591.08
<b>Total Parts (\$\$)</b>	<b>5,264.32</b>	<b>2,604.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	100.00	20.00
3	TUFFKOTE	New	100.00	30.00
4	SPRAY PAINTING	New	1,000.00	600.00
5	LABOUR CHARGES	New	1,000.00	500.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,320.00</b>
				<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >