



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SME 69Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HEADLAMP LH	BROKEN/CUT	\$4,370.00	\$4,091.21
1	HEADLAMP BRACKET LH	NOT NECESSARY	\$280.00	\$0.00
1	FRONT BUMPER	BROKEN/DEFORMED	\$2,800.00	\$2,272.40
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	\$180.00	\$0.00
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	\$180.00	\$0.00
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	\$40.00	\$0.00
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	\$40.00	\$0.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	\$420.00	\$0.00
1	AIR VENT COVER	BROKEN	\$142.00	\$142.00
1	BUMPER SPONGE	BROKEN	\$250.00	\$162.00
1	FOGLAMP MOULDING	CUT	\$450.00	\$352.00
	LESS 5.00% DISCOUNT		(\$457.60)	(\$350.98)
			\$8,694.40	\$6,668.63

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER SENSOR (SN)	SHORTED (1PC ONLY)	\$960.00	\$240.00
1	SET FRONT BUMPER RADAR SENSOR (SN)	NOT NECESSARY	\$2,980.00	\$0.00
1	FRONT LIP (CARBON FIBER) (SN)	BROKEN	\$1,600.00	\$600.00
1	SIDE LIP (CARBON FIBER) (SN)	NOT NECESSARY	\$1,700.00	\$0.00
1	AIR VENT (CARBON FIBER) (SN)	BROKEN	\$850.00	\$650.00
1	FRONT CANNARD (CARBON FIBER) (SN)	NOT NECESSARY	\$950.00	\$0.00
1	WRAP (SN)	NECESSARY	\$1,200.00	\$400.00
			\$10,240.00	\$1,890.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK REAR WIRING AND LIGHTING SYSTEM		\$500.00	\$80.00
	REMOVE AND RENEW SENSOR		\$350.00	\$50.00
	DIAGNOIS CHECK AND CLEAR FAULT CODE		\$400.00	\$80.00
	TRANSFER PARTS, ATTACHMENT FROM OLD REAR TO NEW	NOT NECESSARY	\$500.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REINSTALL THE WRAP		\$1,200.00	\$150.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW PART		\$800.00	\$300.00
	SPRAY PAINTING ON AFFECTED AREAS		\$800.00	\$250.00
			\$4,550.00	\$910.00
GRAND TOTAL			\$23,484.40	\$9,468.63
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$7,550.00
Report Ref No: CS/AWA24090215/Evp3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.