



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914	Ref: CS/AWA24090215/Evp3e2 Date: 24/09/2024 Code: AWA
---	---

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5509L	Veh. Inspected	SME 69Y
Policy No.	BVFCB0014402401	Coverage	0
Claim No.	XD 5509 L/HLF	Excess	\$0.00
Assign From	HEW LEE FONG	Assign Date	12/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ CLA45S	C.C	1991
Engine No.	13998060011717	Year of Reg.	23/04/2021
Chassis No.	W1K1183542N158997	Colour	GREY
Odometer	33910 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35Z R19	CONTINENTAL	6
L/H Front Tyre	255/35Z R19	CONTINENTAL	6
R/H Rear Tyre	255/35Z R19	CONTINENTAL	6
L/H Rear Tyre	255/35Z R19	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2024	Inspection Date	13/09/2024
Survey held at	REGNANT AUTOMOTIVE PTE LTD - 53 UBI AVENUE 1, #01-09, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days