4/17/25, 10:02 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24090218/EUA3Q2

Date: 17/04/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230044183 **Claimant Vehicle** SMV9206U SNK8754G

Insured Vehicle No: No:

Date of Loss: 12/09/2024 Nature of Claim: TP Claim No: 4602792272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMV9206U Reg No:

AUDI A5 SPORTBACK, 2.0 TFSI S TRONIC Make & Model: Engine No: DEM025629

(110 KW) (A) Reg. Date: 27/10/2020 (Man. Year: 2020) Chassis No: WAUZZZF51MA003541

Colour: Black Odometer: 74605 km

Engine Capacity: 1984 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Rear Right Side: Front Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,180.00	0.00	3,180.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,772.00	2,822.00	1,950.00	40.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,952.00	2,822.00	5,130.00	64.51
	+ GST 9.00/9.00% (S\$)	715.68	253.98	461.70	64.51
	Nett Amount (S\$)	8,667.68	3,075.98	5,591.70	64.51
	+ Loss of Use (1.0 x	S\$100.00/day) (S\$)	100.00		
	+ Car Rental (4.0 x S\$150.00/day	+ 9.00% GST) (S\$)	654.00		
	+ D	oc/Search Fee (S\$)	2.18		
		Nett Liability (S\$)	3,832.16		

INSPECTION

Date of Assignment: 17/09/2024

Premium Automobiles Pte Ltd (HQ)

17/09/2024 55 UBI ROAD 1 Date Inspected: Inspected At: Singapore 408699

Estimated Period of Repair: 5.0 days

CHEN TSUE YEE Manager: NA MENG YAN Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,945.00 FS	*- FS
2	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	56.00 FS	*- FS
3	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	29.00 FS	*- FS
4	1		*SUNDRIES	Not Necessary	150.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	ett.	Total Parts (S\$)	3,180.00	0.00
			Report was unsubmitted du	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			*
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	360.00	360.00
2	TO REMOVE AND REINSTALL REAR BUMPER TO REPAIR RHS REAR FENDER RE-ORGANZIE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,750.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	1,800.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
5	TO REAPPLY PAINT COATING AND PPF ON AFFECTED AREA	New	570.00	570.00
	Gross Labou	4,772.00	2,822.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >