

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090219/EUA3Q2  
Date: 05/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826\_03  
Claimant Vehicle No : SMT9778X Insured Vehicle No : SNF4425J  
Date of Loss: 08/09/2024 Nature of Claim: TP Claim No: MFL2024D0010584

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT9778X  
Make & Model: KIA SORENTO, 2.2 D CRDI 2WD S/R (A) Engine No: D4HBLH241627  
Reg. Date: 27/07/2020 (Man. Year: 2020) Chassis No: KNAPH81BML5650845  
Colour: Blue Odometer: 59288 km  
Engine Capacity: 2199 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,793.00	1,888.00	2,905.00	60.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	1,630.00	4,890.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,313.00	3,518.00	7,795.00	68.90
+ GST 9.00/9.00% (S\$)	1,018.17	316.62	701.55	68.90
Nett Amount (S\$)	12,331.17	3,834.62	8,496.55	68.90
+ Car Rental (4.0 x S\$140.00/day + 9.00% GST) (S\$)		610.40		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,447.20		

INSPECTION

Date of Assignment: 17/09/2024  
Date Inspected: 17/09/2024 Inspected At: CYCLE & CARRIAGE KIA PTE LTD (HQ)  
330 UBI ROAD 3  
Singapore 408650  
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2025)
Parts:	M1-SUV	KIA SORENTO 2.2 D CRDI 2WD S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT9778X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LOGO ASSY -KIA SUB	Not Necessary	60.00 FS	*- FS
3	1		*EMBLEM -SORENTO	Not Necessary	28.00 FS	*- FS
4	1		*EMBLEM -ECO DYNAMICS	Not Necessary	37.00 FS	*- FS
5	1		*COVER -RR BUMPER ,UPR	Broken	686.00 FS	*686.00 FS
6	1		*COVER -RR BUMPER LWR	Cut	677.00 FS	*677.00 FS
7	10		*CLIP BUMPER	Necessary	10.00 FS	*10.00 FS
8	1		*BRACKET ASSY -RR BUMPER SIDE ,LH	Not Necessary	22.00 FS	*- FS
9	1		*BRACKET ASSY -RR BUMPER SIDE ,RH	Not Necessary	22.00 FS	*- FS
10	1		*SKID PLATE -RR BUMPER	Cut	103.00 FS	*103.00 FS
11	1		*CAP-RR HOOK	Not Necessary	5.00 FS	*- FS
12	1		*COVER -BLANKING RR FOG ,LH	Not Necessary	44.00 FS	*- FS
13	1		*COVER -BLANKING RR FOG ,RH	Not Necessary	44.00 FS	*- FS
14	1		*LAMP ASSY -REAR FOG & R/REFL ,LH	Not Necessary	134.00 FS	*- FS
15	1		*LAMP ASSY -REAR FOG & R/REFL ,RH	Not Necessary	134.00 FS	*- FS
16	4		*ULTRASONIC SENSOR ,S.P.A.S	Not Necessary	748.00 FS	*- FS
17	1		*WIRING HARNESS -R.P.A.S	Not Necessary	357.00 FS	*- FS
18	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	33.00 FS	*- FS
19	1		*RAIL ASSY -REAR BUMPER	Bent	392.00 FS	*392.00 FS
20	1		*COVER ASSY -RR BPR UNDER LH	Not Necessary	30.00 FS	*- FS
21	1		*MUFFLER ASSY -REAR	Not Necessary	1,177.00 FS	*- FS
					F=Franchise part. S=SpcNett.	
					Total Parts (S\$)	4,793.00 1,888.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE	New	280.00	280.00
2	TO CHECK WIRING AND ELECTRICAL SYSTEM	New	100.00	80.00
3	TO REMOVE & REINSTALL FLOOR BOARDS ,CARPETS TRIMS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	0.00
4	TO REPLACE LOGO ,EMBLEM ,UPR & LWR REAR BUMPER ,CLIPS ,SIDE BRACKETS, SKID PLATE ,CAP HOOK ,LH & RH REFLECTOR LAMP & COVER ,SENSORS,WIRING HARNESS ,ANTENNA BEAM ,LH UNDER COVER ETC -TO REPAIR TAILGATE PANEL & REAR END PANEL STRAIGHTEN,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	2,560.00	640.00
5	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE PANEL,UPPER REAR BUMPER & REAR END PANEL)	New	2,200.00	550.00
6	TO CHECK ,TEST & REFIT REVERSE SENSORS	New	100.00	80.00
7	TO REMOVE & REPLACE EXHAUST MUFFLER	New	640.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,520.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >